

Masoor House To To1

MMJSTY

Schedule XLV-Form No. 134 (Sec)

NITU KUMARI

2.33.10 Kishoregaj-1

DIVISION

R.O.D Keshadhasan

SUB-DIVISION

3077

MEASUREMENT BOOK

Agreement No. - 2006/MMJSTY/SBP/2020-21

Particulars	Details of actual measurement				Contents of area
	No.	L	B	D.	
3rd year maintenance Bill					
Name of work - Ma 300x house to					
TO1 under MMLSY (SC)					
Name of Agency - Nitya Kumari Kishangori					
Agreement No - 200/MMLSY/SED/2020-21					
Actual Date of Completion - 15-05-2021					
(1) Restoration of Rain cuts					
with soil -- all complete					
$22 \times 4.80 \times 0.80 \times 0.300 = 25.344 \text{ m}^3$					
$5 \times 3.50 \times 0.90 \times 0.300 = 4.725 \text{ m}^3$					
$3 \times 1.0 \times 0.60 \times 0.300 = 0.54 \text{ m}^3$					
30.61 m^3					
$30.61 \text{ m}^3 @ \text{RS } 404 = 06/\text{m}^3 \quad \text{RS } 12368 = 00$					
(2) maintenance of Earthen					
shoulder (Filling with fresh					
Selected soil) -- all complete					
$30 \times 5.50 \times 0.80 = 132.0 \text{ m}^2$					
$11 \times 3.70 \times 0.90 = 36.63 \text{ m}^2$					
$1 \times 1.80 \times 1.0 = 1.80 \text{ m}^2$					
170.43 m^2					
$170.43 \text{ m}^2 @ \text{RS } 60 = 48/\text{m}^2 \quad \text{RS } 10308 = 00$					
(3) Repair to pot holes					
with mix seal surfacing					
---- all complete					
$10 \times 2.80 \times 0.75 = 21.0 \text{ m}^2$					
$13 \times 1.10 \times 0.65 = 9.30 \text{ m}^2$					
30.30 m^2					
$30.30 \text{ m}^2 @ \text{RS } 239 = 08/\text{m}^2 \quad \text{RS } 7244 = 00$					
C.O. RS 29920 = 00					

Continuation

