

Name of work - Const. of Road & CD work from R.W.D.
Road Karamnadi to Mandol Tal Daspur

Pol.

MHGSY (SC)

Schedule XLV-Form No. 134

Head - MHGSY

Year - 2016-17

R.W.D. Karmalibari

DIVISION

R.W.D. Karmalibari

SUB-DIVISION

15560/16-17

Measurement Book

-1758

Maa Biradu Const

(SC)

4th year maintenance Bill

77

Sch. XLV—Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
name of road:-	Maintenance of road				
	2nd work from RWD Road				
	Karmali to Mandal tola				
	Dostpur,				
Agency:-	Maa Bindu construction, Patner				
Agreement no.:-	15 SBD/16-17				
date of start:-	20.05.2016				
date of completion:-	19.11.2016				
Actual date of completion:-	18.05.2019				
(1) Restoration of rain cuts with					
Soil do -					
	27	13	7.50	$\frac{1.2+1.0}{2} \times 0.30$	42.90
	2	6	7.50	$\times \left(\frac{1.0+0.75}{2} \right) \times 0.30$	15.75
				Total =	58.65 m ²
(2) Making up of Berms/shoulder					
do all complete job -					
	2	5	10.0	$\times \frac{1.10+0.90}{2}$	100.00
	2	12	10.0	$\times \frac{1.20+1.0}{2}$	215.00
				Total =	315.00 m ²
				Limit =	314.89 m ²
(3/4) patch repair over potholes					
with 20mm premium Carpet					
with Seal coat type B1 -					
	21	7	1.00	$\times 0.60$	12.60
	10	7	0.70	$\times 0.60$	4.20
	15	7	0.60	$\times 0.40$	3.60
	13	7	0.90	$\times 0.50$	5.85
	9	7	1.00	$\times 0.90$	8.10

Continuation

ABSTRACT OF COST 4th year maintenance

80

Sch. XLV—Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
name of work - maintenance of Road					
& CD work from RWD Road					
Harmani to Mandal hole					
dist. km.					
Agency - Mac Bindu construction, Patna.					
Agreement no. - 15 SBD / 16-17					
Date of start - 20.05.2016					
Date of completion - 19.11.2016					
Actual date of completion - 18.05.2019					
(1) Restoration of rain cuts with					
Soil 20 -					
Qty vide TMBP - 77, 91 no (1)					
58.65 m ³ @ RS 294.07/m ³ - RS 17,247/-					
(2) making up of Barm / shoulder					
is all complete job					
Qty vide TMBP - 77, 91 no (2)					
314.89 m ³ @ RS 49.48/m ³ - RS 15,581/-					
(3) patch repair over potholes					
with 20mm premix carpet					
with seal coat type 'B' -					
Qty vide TMBP - 78, 91 no (3)					
58.30 m ² @ RS 284.39/m ² - RS 16,580/-					
(4) patch repair over Bituminous					
surface with 20mm premix					
carpet with seal coat type 'B'					
is all complete job					
Qty vide TMBP - 78, 91 no (4)					
58.30 m ² @ RS 284.35/m ² - RS 16,578/-					

Continuation

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
(5/7) Maintenance of CD work do all complete job					
8.4 m wide TMBP-78.91 m	(5/7)				
02 nos @ RS 910.95/m ²					RS 1822 =
(6/8) Maintenance of road 8.4 m do					
8.4 m wide TMBP-78.91 m	(6/8)				
1.02 km @ RS 904.33/km					RS 922 =
(7/9) Maintenance of 300m post 8 km stone do					
8.4 m wide TMBP-78.91 m	(7/9)				
1.02 km @ RS 932.71/km					RS 442 =
(8/10(i)) Cutting of branches of tree do all complete job					
8.4 m wide TMBP-78.91 m	(8/10)				
02 nos @ RS 80.68/40					RS 161 =
(9/10(ii)) Cutting of shrubs from roadway do					
8.4 m wide TMBP-78.91 m	(9/10)				
07 nos @ RS 4.95/m ²					RS 35 =
(10/10(iii)) Trimming of grass & weeds 8.4 m wide TMBP-78.91 m	(10/10)				
16.0 m ² @ RS 1.65/m ²					RS 26 =
(11/11) White washing of parapet wall of CD work					
8.4 m wide TMBP-78.91 m	(11/11)				
39.30 m ² @ RS 13.26/m ²					RS 522 =
					RS 69,916 =
1445 10% below of RS 69,916					RS 69,916 =

Continuation

RS 62,924 =

23.05.2020
JE