

ne of work - cost of Road and CD work 4,000
Schedule X.L.V. PROPOSED
from Mompoochuk to Lokrampur Musa Sidi
House to Sidi P. H. Mompoochuk road
BILAR P. W. D. under MUSOY (se) Head

R. W. D., *Machabeani*

25-361 | 2017-18

SUB-DIVISION

MEASUREMENT BOOK 1972

Mr. Jayback
The

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	

5th year Maintenance.

Name of work - Maint of Road from

PMCHY Road Mokrampur

Hussain Sah House to Saphi

Tal Mokrampur.

Agency :- Sri Jayaboth Jha.

Agm No:- 95/SBD/2017-18

D.O.S. - 14.10.2017

Actual D.O.C - 25.06.2018

MEASUREMENT -

1. Restoration of rainments

Berms width 30cm - Nil.

2. Maintenance of earthen

Dam

$$27 \times 30.00 = 810.00\text{m}^2$$

$$142.00 \times 21.00\text{m}$$

$$831.00\text{m}^2$$

3. Maintenance of C.D. Works

$$142 = 2100\text{m}^2$$

4. White washing on parapet

Wall of C.D.

$$2 \times 2 \times 6.15 \times 0.60 = 14.76\text{m}^2$$

$$2 \times 2 \times 6.15 \times 1.20 = 29.52\text{m}^2$$

$$2 \times 2 \times 6.15 \times 0.40 = 9.80\text{m}^2$$

$$2 \times 4 \times 0.40 \times 0.60 = 1.92\text{m}^2$$

$$56.04\text{m}^2$$

By
✓ 19/6/23

17 NOV.
SZ.
19/6/23
AB

Particulars	Details of actual measurement				Contents of area	
	No.	L.	B.	D.		
<u>Abatement of cast-</u>						
<u>1/6 Maintenance of C-D</u>						
<u>Length:</u>						
<u>Qty. value TMB Pn030</u>						
<u>= 831.00 m</u>						
<u>CMS = 10/m</u>						
<u>1745 =</u>						
<u>2/7 Maintenance of C-D wall.</u>						
<u>Qty. value TMB Pn030</u>						
<u>2 m2. CMS = 33 each = 1899</u>						
<u>3/11 White washing of the</u>						
<u>parapet wall of C-D</u>						
<u>Qty. value TMB Pn030</u>						
<u>= 56.04 m²</u>						
<u>CMS = 01/m² — 1785 =</u>						
<u>1785 =</u>						
<u>Less 10% below = 1744.29 =</u>						
<u>1744.29 =</u>						
<u>1744.29 =</u>						
<u>TMB 3986 = 00 only</u>						
<u>Chk by</u>						
<u>20/11/23</u>						
<u>3.E</u>						
<u>05/11/23</u>						
<u>M</u>						
<u>Continuation</u>						