

—X—X—

Sch. XLV-Form No. 134

Item	Restoration of	
	do	62
1 x 24m	x 1.60m x 0.360m =	11.52 m ³
1 x 17.20 m	x 1.30m x 0.360m =	6.98 m ³
1 x 25.00m	x 1.35m x 0.360m =	10.12 m ³
1 x 18.56m	x 1.82m x 0.360m =	10.10 m ³
1 x 13m	x 1.73m x 0.360m =	6.75 m ³
Total =		45.47 m ³

Continuation 128.51 m^2

ABSTRACT of COST

34

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Item 1/1 Restoration of					
do do			EI		
Qty. vide TMBP					
45.74 m ² @ Rs 358.02/m ²					16376.00
Item 2/2 Maint. of earthen					
do do			EI		
Qty. vide TMBP					
126.83 m ² @ Rs 54.22/m ²					10686.00
Item 3/5 Patch Repair					
do do			EI		
Qty. vide TMBP					
16.38 m ² @ Rs 320.75/m ²					5254.00
Item 4/7 Maint. of culverts					
do do			EI		
Qty. vide TMBP					
2 Nos @ Rs 1057.98/No					2116.00
Item 5/8 Maint. of Road					
do do			EI		
Qty. vide TMBP					
0.02 Km @ Rs 1020.54/Km					20.41
Item 6/10 Maint. of 20m					
do do			EI		
Qty. vide TMBP					

Continuation



Continuation