

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
3rd year Maintenance					
Name of Road $\rightarrow$					
<u>Reo Sadak</u>					
<u>to Saidpur Chaur</u>					
<u>to la tak</u>					
Agency $\rightarrow$					
<u>Rakesh Kumar</u>					
Agreement No -					
<u>MM4sy/ISD-44/</u>					
<u>2021-22</u>					
Rate -					
<u>Schedule</u>					
L =					
<u>0.904 Km</u>					
Agreement value -					
<u>6378925.00</u>					
Date of work order -					
<u>29/9/21</u>					
Date of comp -					
<u>28/9/22</u>					
1. Restoration of Rain cuts					
<u>$2 \times 2.18 \times 1.63 \times 0.30 = 2.13 \text{ m}^3$</u>					
<u>$3 \times 4.35 \times 1.58 \times 0.30 = 6.18 \text{ m}^3$</u>					
<u>$4 \times 4.65 \times 1.61 \times 0.30 = 8.98 \text{ m}^3$</u>					
<u>$2 \times 2.56 \times 1.48 \times 0.30 = 2.27 \text{ m}^3$</u>					
<u>$3 \times 5.18 \times 1.78 \times 0.30 = 8.29 \text{ m}^3$</u>					
<u>$3 \times 4.65 \times 1.61 \times 0.30 = 6.73 \text{ m}^3$</u>					
<u>Total = 34.58 m³</u>					

BF-As-33381-00

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
4. Providing & laying of hot applied thermoplastic					
vide TMB page No - 35					
180.8 m ² @ 721.95 =					130529.00
5. Maintenance of bitumen surface road patch repair on already filled pot holes.					
vide TMB page No - 35 to 36					
31.69 m ² @ 274.89 =					8695.00
6. Maintenance of Hum pipe culverts					
vide TMB page No - 36					
1.00 No @ 1166.58 =					1167.00
7. Maintenance of slab type of culverts					
vide TMB page No - 36					
1.00 No @ 2394.96 =					2395.00
8. Maintenance of 200 meter 8 kms stone					
vide TMB page No - 36					
0.90 km @ 748.22 =					673.00
				Rs	176,840.00
Add 1% Labour				Rs (+)	1768.40
Add 12% GST				Rs (+)	21220.80
				Total = Rs	199829.20

Sham
7/4/25
RE

Continuation