

कार्यपालक अभियन्ता का कार्यालय
ग्रामीण कार्य विभाग, कार्य प्रमण्डल, बक्सर

पत्रांक 581 /

बक्सर, दिनांक 17-4-25 /

प्रेषक:-

कार्यपालक अभियन्ता,
ग्रामीण कार्य विभाग,
कार्य प्रमण्डल, बक्सर।

सेवा में,

नोडल पदाधिकारी,
3054 (M.R) कोषांग,
बिहार, पटना।

विषय:- शीर्ष 3054 नई अनुरक्षण नीति-2018 अंतर्गत Initial Rectification and Surface renewal. कराये गये कार्य हेतु अधियाचना के संबंध में।

महाशय,

उपर्युक्त विषयक कहना है कि विहित प्रपत्र में संलग्न विवरणी के अनुसार शीर्ष Mr 3054 New Maintenance Policy-2018. अन्तर्गत Initial Rectification and Surface renewal. कराये गये कार्य हेतु राशि की आवश्यकता है।

अतः कार्यहित में अनुरोध है कि उक्त अधियाचित राशि उपलब्ध कराने की कृपा की जाय ताकि कराये जा रहे कार्यों का विपत्र भुगतान किया जा सके।

- अनु०:- (1) अधियाचना प्रपत्र
(2) IRI Value Report
(3) Map
(4) प्रमाण-पत्र।

विश्वासभाजन



17.4.25

कार्यपालक अभियन्ता
ग्रा०का०वि०, कार्य प्रमण्डल,

बक्सर

Om
17.4.25

FORM GFR 19-A

(See Government of India's Decision (I) below Rule- 150)

Form of Utilization Certificate upto date of 17.04.2025

Name of Scheme :- MR NEW MAINTENANCE POLICY-2018.

Sl. No.	Name of Scheme	Sanction No. & Date with Amount (Rs.In lacs)	Amount Received (Rs.In Lacs)	Particulars
		Through C.F.M.S. Received	-	
1	MR NEW MAINTENANCE POLICY 2018.	<u>BF up to 2024-2025</u> <u>Lt No-29 dt-30.03.2025</u> <u>12741.89335</u>	12741.89335	Certified that Allotment Received during the year 2024-2025 Throught C.F.M.S. Rs.12741.89335 lacs of grants-in- favour of Executive Engineer, R.W.D.(W) Division, Buxar. Bihar a sum of Rs.12718.77567 lacs has been utilized for the purpose of MR NEW MAINTENANCE POLICY-2018. schemes as given in the margin for which it was sanctioned and that the balance of Rs.23.11788 lacs (allotment surrender vide Lt no-460 dt- 21.03.2025 amount Rs.17.76709) remaining unutilized at the end of the period under report.
		Total Rs. =	12741.89335	

- 2 Certified that I have satisfied myself that the conditions on which the grants- in - aid was sanctioned have been duly fulfilled. are being fulfilled and that I have exercised the following checks to see that the money was actually utilized for the purpose for which it was sanctioned.

Kind of Checks exercise:-

- Works have been supervised by Executive Engineer/ Superintending Engineer
- Periodical inspection has been conducted by Executive Engineer/ Superintending Engineer
- Construction materials have been tested.
- Measurements have been recorded in the MBs and test check conducted by the Assistant Engineer/ Executive Engineer.
- All other codal formalities have been observed.

3 **Physical progress achieved:-**

- Construction of Road works.
- Construction of CD works.


 D.A.O.
 R.W.D. (W) Division,
 Buxar


 17.4.25
 Executive Engineer
 R.W.D. (W) Division.
 Buxar
 17.4.25

Name of Division:- RWD Works Division Buxar.

Rural Works Department
MR NEW MAINTENANCE POLICY-2018. ALLOTMENT REQUISITION

Date-17.04.2025

SL. No.	Year	Name of Road	Name of Contractor (In English)	Project Id	Administrative Sanction		Agreement Amount (In Lacs)		Value of FRI (in mm/km)	Thickness of Bitumen Layer (in mm)	Value of Bitumen Content in Percentage	Allotment Received (in Lacs)	Total Expenditure as per MIS (in Lacs)	Value of Measurement (in Lacs)	Current Demand (in Lacs)	Remarks
166	2023-24	Buxar Jila antargat buxar prakhand me amarpur gram ke antargat jaati deira me yogendra ram,musafir Daswan thha harinarayan manjhi ke ghar se bandh hote hue Sanichra baba ke pas mukhya sarak tak path nirman.	Narendra Kumar	10401905001	2.000	83.08400	40.57900	10.45455	2088	25	5%	0.00000	0.00000	40.57900	40.57900	Physically complete

D.A.O.
RWD Works Division
Buxar

Executive Engineer
RWD Works Division
Buxar

17.4.25

CM
17.4.25


कार्यपालक अभियंता का कार्यालय
ग्रामीण कार्य विभाग, कार्य प्रमंडल, बक्सर

कार्यालय आदेश


प्रमाणित किया जाता है कि बिहार ग्रामीण पथ अनुरक्षण नीती-2018 योजनान्तर्गत Buxar jila antargat buxar prakhand me amarpur gram ke anatargat jaati dera me yogendra ram, musafir paswan ttha harinarayan manjhi ke ghar se bandh hote hue Sanichra baba ke pas mukhya sarak tak path nirmaan. पथ का कार्य गुणवत्ता एवं विशिष्टियों के अनुरूप पूर्ण कराया गया है। पथ के मापीपुस्त की जाँच मेरे द्वारा 10 प्रतिशत, सहायक अभियंता द्वारा 50 प्रतिशत एवं कनीय अभियंता के द्वारा शत प्रतिशत किया गया है।


17/04/25

कनीय अभियंता
ग्रामीण कार्य विभाग
कार्य प्रशाखा बक्सर


17/04/25

सहायक अभियंता
ग्रामीण कार्य विभाग
कार्य अवर प्रमंडल बक्सर


17.4.25

कार्यपालक अभियंता
ग्रामीण कार्य विभाग
कार्य प्रमंडल, बक्सर

Name of Road:-Buxar jila antargat buxar prakhand me amarpur gram ke anatar gat jaati dera me yogendra ram,musafir paswan ttha harinarayan manjhi ke ghar se bandh hote hue Sanichra baba ke pas mukhya sarak tak path nirmaan. Contractor Name:-Narendra Kumar

Date	Time	Section No.	Length in km	Bumps in mm	Speed Rate	QR min/km	IRI mm/km	CATEGORY ROAD	Latitude	Longitude	Event
17/4/25	11:03:15	69	0.1	210	10.1	2100	1962	G	25.63031	84.068656	Normal
17/4/25	11:04:41	69	0.1	240	10.1	2400	2207	G	25.63034	84.067817	Normal
17/4/25	11:05:13	69	0.1	230	10.1	2300	2125	G	25.63044	84.06607	Normal
17/4/25	11:06:07	69	0.1	250	10.1	2500	2288	G	25.63038	84.066066	Normal
17/4/25	11:08:01	69	0.1	200	10.1	2000	1880	G	25.62375	84.065138	Normal
17/4/25	11:09:03	69	0.1	230	10.1	2300	2125	G	25.63025	84.065268	Normal
17/4/25	11:10:25	69	0.1	110	10.1	2200	2044	G	25.62913	84.063263	Normal
17/4/25	11:11:01	69	0.1	210	10.1	2100	1962	G	25.62898	84.062998	Normal
17/4/25	11:12:51	69	0.1	210	10.1	2100	1962	G	25.62896	84.062857	Normal
17/4/25	11:13:05	69	0.1	240	10.1	2400	2207	G	25.62895	84.062866	Normal
17/4/25	11:14:08	69	0.1	230	10.1	2300	2125	G	25.62811	84.061475	Normal
17/4/25	11:16:09	69	0.1	250	10.1	2500	2288	G	25.62814	84.061413	Normal
17/4/25	11:16:56	69	0.1	200	10.1	2000	1880	G	25.62808	84.061306	Normal
17/4/25	11:18:36	69	0.1	230	10.1	2300	2125	G	25.62763	84.060368	Normal
17/4/25	11:19:09	69	0.1	110	10.1	2200	2044	G	25.62653	84.058774	Normal
17/4/25	11:20:01	69	0.1	210	10.1	2100	1962	G	25.6266	84.058588	Normal
17/4/25	11:21:46	69	0.1	210	10.1	2100	1962	G	25.62611	84.057508	Normal
17/4/25	11:22:17	69	0.1	240	10.1	2400	2207	G	25.62583	84.057176	Normal
17/4/25	11:23:05	69	0.1	230	10.1	2300	2125	G	25.62587	84.057117	Normal
17/4/25	11:24:15	69	0.1	250	10.1	2500	2288	G	25.62577	84.056923	Normal
		length	2.000								

Rashedul Karim
17.4.25

17/04/25
J.E

17/04/25
AE

17.4.25
EE

$$Y = 0 * X^2 + 0.816 * X + 249$$

$$X = 2125$$

$$Y = 2044$$

(R) RURAL ROAD

Good Average Poor

<4000 4001-5000 >5001

IRI value=2088

Machine ID=19195

File: C:\Users\7SUPRYANAND MISHRA\Desktop\06031354.xlsx Section No.: 69, Eqn: test

Name of Customer: NARENDRA KUMAR, Name of Work/ Road: BUXAR JILA ANTRAGAT BUXAR PRAKHAND ME

mm/
km



880 0 0.1 0.2 0.3 0.4 0.5 0.6 0.7 0.8 0.9 1 1.1 1.2 1.3 1.4 1.5 1.6 1.7 1.8 1.9 2

Distance * 1000 m

Kantilal
19.04.2008

17/04/25
J.E

17/04/25
AE

17.4.25
E E