

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
M/2004 Maintenance of Road from Laskari Biser Sadak Singas Aus to Hanzeli Tola under MNSY Gen					
Agency: Pradip Kumar Medhebar.					
Ag. No. - 11530/2022-23					
D. of Start - 17.06.2022					
A.D. of Comp. - 28.03.2024					
① Making up of Berms/Shoulders stripping excess soil - - - -					

4 x 8.20 x 1.50 -	32.80 m ²
6 x 7.45 x 0.70 -	31.29 m ²
5 x 9.25 x 0.50 -	24.13 m ²
2 x 15.00 x 1.15 -	29.75 m ²
3 x 6.80 x 0.95 -	19.38 m ²
	156.35 m ²

② Maintenance of 1500 mm HP Culvert - - - -	
- - - - -	
	1.00 Nos

③ Maintenance of Road Signs - - - -	
	0.05 km

Continuation

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
	05			B	9741.00
④ Maintenance of 200m					
and 2m stone					
- - - - - 012					
Ampl. by 05 D. 16 N4					
@ 583.84/m				K	35.00
					9776.00
Add for GST @ 12%				K	1173.00
Add for L. Cost @ 1%				B	98.00
Add for S. Fees				K	105.00
					11152.00
Less for below @ 5%				K	558.00
					10594.00

7573/2015

RE

Udeshi Shingam

15/3/25
A/E

Material Statement

6/m → 21.0 m²

Continuation