

5th year maintenance

60

Sch. XLV-Form No. 134

[illegible]

(1) Restoration at Paimouts			
do-do			
10 x	15.0 x	1.10 x	0.30 = 49.50
06 x	19.0 x	1.0 x	0.30 = 34.20
21 x	12.50 x	1.10 x	0.30 = 86.63
12 x	22.0 x	1.10 x	0.30 = 87.12
2 x	05.0 x	1.10 x	0.3 = 3.30
			<u>260.75</u>
(2) making at Bemp/Shoulder			
stippling excess soil			
do-do			
12 x	22.0 x	1.10	= 290.40
10 x	16.50 x	1.0	= 165.0
16 x	18.0 x	1.20	= 345.60

Continuation

Details of actual measurement				Contents of area
	L	B	D	
(1) Filling at fairways				
do do				
Qty vide TMB				
Page No - 60	=	260.38 m ²		
@ 7 144.14 m ²			7	108856.0 34853.0
(2) Making ab berm/shoulder				
stripping do do				
Qty vide TMB				
Page No - 61	=	1452.94 m ²		
@ 7 58.37 m ²			7	84808.0
(3) Repair ab pot holes filled				
do do				
Qty vide TMB				
Page No - 61	=	25.22 m ²		
@ 7 10354.58 m ²			7	261143.0
(4) Patch repair over pot				
holes do do				
Qty vide TMB				
Page No - 61	=	336.33 m ²		
@ 7 259.57 m ²			7	87301.0
(5) Main tance ab C/D works				
do do				
Qty vide TMB				
Page No - 62	=	7 NOS		
@ 7 1117.01 NOS			7	7819.0
(6) Maintenance ab C/D works				
do do				
Qty vide TMB				

Continuation

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Page No - 62 = 1 NOS					
@ 7 2309.04 NOS				7	2309.0
(7) Cutting at branches					
do do					
Qty vide TMB					
Page No - 62 = 6 NOS					
@ 7 117.18 NOS				7	703.0
(8) Cutting at shrubs					
do do					
Qty vide TMB					
Page No - 62 = 29 NOS					
@ 7 6.54 NOS				7	190.0
(9) Trimming at grass					
do do					
Qty vide TMB					
Page No - 62 = 62.40 m ²					
@ 7 2.18/m ²				7	136.0
(10) White washing at parapet					
do do					
Qty vide TMB					
Page No - 62 = 146.86 m ²					
@ 7 16.48/m ²				7	2420.0
(11) Road marking with Hot					
do do					
Qty vide TMB					
Page No - 62 = 574.0 m ²					
@ 7 850.93 m ²				7	488434.0
					1043519.0

Continuation

05/08/2025
JE

