

Name of Road :- Mathura Buzhiya Prusya Gada
TO Gadar Singh Ke Tota Dhamak
Schedule XLV-Form No. 134 Tota

Name of Agency :- J.M. Infra (SC)

DIVISION

Block :- Sidhawaliya

SUB-DIVISION

K.J.B.P.D - 560

MEASUREMENT BOOK

4th Year Maintenance Bill

66

Sch. XLV—Form No. 134

[illegible]

Measurement

① Restoration of Rain cuts/Berms.

$$5 \times 5.5 \times 0.85 \times 0.3 = 7.01 \text{ m}^3$$

$$5 \times 10.3 \times 0.8 \times 0.30 = 12.36 \text{ m}^3$$

$$4 \times 8.5 \times 0.85 \times 0.30 = 8.67 \text{ m}^3$$

$$4 \times 8 \times 0.8 \times 0.30 = 7.68 \text{ m}^3$$

$$35.72 \text{ m}^3$$

② Making up Berms/shoulders.

$$9 \times 15 \times 0.85 = 114.75 \text{ m}^2$$

$$11 \times 10.4 \times 0.85 = 97.24 \text{ m}^2$$

$$12 \times 9.5 \times 0.8 = 91.20 \text{ m}^2$$

$$9 \times 25 \times 0.85 = 191.25 \text{ m}^2$$

$$5 \times 13 \times 0.8 = 52.00 \text{ m}^2$$

$$3 \times 30 \times 0,85 = 76,5 \text{ m}^2$$

$$622.94 \text{ m}^2$$

Continuation

Continuation

Abstract of Cost

68

Sch. XLV—Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
① Restoration of Raincuts/Berms.					
85.72 m ³ VTMB Page No (66)					
@ Rs 379.59/m ³ —					13559.00
② Making up of Berms/shoulder.					
622.94 m ² VTMB Page No (66)					
@ Rs 57.01/m ² —					35514.00
③ Repair of Poles filled with 35mm					
46.11 m ² VTMB Page No (67)					
@ Rs 455.86/m ² —					21020.00
④ Patch repair over bituminous.					
46.11 m ² VTMB Page No (67)					
@ Rs 283.76/m ² —					13084.00
⑤ Maintenance of Road signs					
0.785 Km VTMB Page No (67)					
@ Rs 1054.28/Km —					828.00
⑥ Maintenance of 200m aid.					
1.57 Km VTMB Page No (67)					
@ Rs 688.17/Km —					1080.00
⑦ Cutting of branches of tree					
1 No VTMB Page No (67)					
@ Rs 106.12/each —					106.00
⑧ Cutting of Shrubs from Roadway.					
5 No. VTMB Page No (67)					
@ Rs 6.51/each —					33.00
⑨ Trimming of grass and weeds.					
494.6 m ² VTMB Page No (67)					
@ Rs 2.17/m ² —					1073.00

Continuation

Continuation