

Chandaini to Daulatpur (SC)

SANJAY JI (SIHRAHUA)

MMGSY (SI)

**Schedule XLV Form No. 134.**

Sanjay Kumar (Sihraha)

Executive Engineer R.W.D. Work **DIVISION**

Tekari

Assistant Engineer R.W.D. Work **SUB-DIVISION**

Konch.

**Measurement Book**

936

Name of Work-

Situation of Work-

Agency by which work is executed-

Date of Measurement-

No. and date of agreement

(These four lines should be repeated at the commencement of the measurement relating to each work)

| Particulars                              | Details of actual measurement |    |    |    | Contents of area |
|------------------------------------------|-------------------------------|----|----|----|------------------|
|                                          | No.                           | L. | B. | D. |                  |
| NAME OF WORK:- CONSTN of ROAD            |                               |    |    |    |                  |
| FROM CHANGINI JAMUN TO                   |                               |    |    |    |                  |
| Daudpur under MNCASy                     |                               |    |    |    |                  |
| Scheme (K) ✓                             |                               |    |    |    |                  |
| Agency:- SANT JAY KUMAR ✓                |                               |    |    |    |                  |
| Agreement NO:- 21/137/MNCASy (K) 21-22 ✓ |                               |    |    |    |                  |
| Commencement of work:- 15/09/21 ✓        |                               |    |    |    |                  |
| Completion of work:- 14/9/22 ✓           |                               |    |    |    |                  |

|                                                |  |  |  |  |  |
|------------------------------------------------|--|--|--|--|--|
| (1) CONSTN of Benchmarks                       |  |  |  |  |  |
| Reference pillars -- as per spec -- 2.409 KM ✓ |  |  |  |  |  |
| (2) CONSTN of Reference pillars                |  |  |  |  |  |
| Burgers -- as per spec -- 2.409 KM ✓           |  |  |  |  |  |
| (3) cleaning and grubbing                      |  |  |  |  |  |
| road land -- as per spec                       |  |  |  |  |  |
| 30 x 30M x 7.00 -- 6300.00M <sup>2</sup> ✓     |  |  |  |  |  |
| 30 x 30M x 7.00 -- 6300.00M <sup>2</sup> ✓     |  |  |  |  |  |
| 20 x 30M x 7.00 -- 4200.00M <sup>2</sup> ✓     |  |  |  |  |  |
| 1 x 9M x 7.00 -- 63.00M <sup>2</sup> ✓         |  |  |  |  |  |
| 16863.00M <sup>2</sup> ÷ 10000 = 1.69 Hect ✓   |  |  |  |  |  |

Continuation

## Sch. XLV-Form No. 134

| Particulars                                                                            | Details of actual measurement |    |    |    | Contents of area |
|----------------------------------------------------------------------------------------|-------------------------------|----|----|----|------------------|
|                                                                                        | No.                           | L. | B. | D. |                  |
| (1) Restoration of<br>Rain cils/Berms.<br><del>do do</del>                             |                               |    |    |    |                  |
| 140.27 m <sup>2</sup> Ply TMB Page<br>No-81/a                                          |                               |    |    |    |                  |
| @ ₹ 404.06/m <sup>2</sup> - ₹ 56677=00                                                 |                               |    |    |    |                  |
| (2) Making up Berms/<br>Shoulder-dod                                                   |                               |    |    |    |                  |
| 778.0 m <sup>2</sup> Ply TMB Page (82)<br>02                                           |                               |    |    |    |                  |
| @ ₹ 60.28/m <sup>2</sup> - ₹ 46898=00                                                  |                               |    |    |    |                  |
| (3) Repair of Pot                                                                      |                               |    |    |    |                  |
| Filled with 7mm<br>WBM X 1.25 <del>do</del>                                            |                               |    |    |    |                  |
| 0.315 m <sup>3</sup> Ply TMB Page (82)<br>3                                            |                               |    |    |    |                  |
| @ ₹ 9056.76/m <sup>3</sup> - ₹ 2853=00                                                 |                               |    |    |    |                  |
| (4) Patch repair<br>over Pot hole<br>with 200mm<br>Pewix <del>do do</del>              |                               |    |    |    |                  |
| 107.52 m <sup>2</sup> Ply TMB Page<br>No-(82)/4                                        |                               |    |    |    |                  |
| @ ₹ 236.84/m <sup>2</sup> - ₹ 25462=00                                                 |                               |    |    |    |                  |
| (5) Patch repair over<br>Bituminous surface<br>200mm M.S. Seal Surface<br>Continuation |                               |    |    |    |                  |
| C.O ₹ 131891=00                                                                        |                               |    |    |    |                  |

[illegible]

Continuation