

Recd Road. Boli Boli New Taingo to Tain Bigha

Schedule XLV-Form No. 134

K.M.G.S.Y - (MD B) Anushree

E.E. R.W.D. Wux Ayanganah **DIVISION**

A.E. Ayanganah **SUB-DIVISION**

MD 14504

MEASUREMENT BOOK

Agency - Rajesh Kr Singh



Sch.XLV-Form No. 134

Particulars	Details of actual measure				Contents of area
	No.	L.	B.	D.	

1st YEAR maintenance

Name of Work → constr of Rd from Rea
Rd Bail Barahi near
thanawa to Jainbigha.

Agency - Rakesh Kr. Singh

Agreement - 51 SBA/2023-24

A.O.S - 05-01-2024

A.O.C - 28-09-2024

maintenance of year 28-09-24

se 27-9-25

U) making up the Berms should
der stripping excess soil
from the shoulder -

$$5 \times 5 \times 1.05 = 26.25 \text{ m}^2$$

$$2 \times 10 \times 0.90 = 18.00 "$$

$$2 \times 6 \times 1.00 = 12.00 "$$

$$2 \times 5 \times 0.85 = 10.20 "$$

$$5 \times 4 \times 0.95 = 19.00 "$$

$$2 \times 10 \times 0.78 = 15.60 "$$

$$2 \times 4 \times 1.10 = 8.80 "$$

$$2 \times 6 \times 1.00 = 12.00 "$$

$$2 \times 5 \times 1.038 = 10.38 "$$

$$2 \times 6 \times 1.01 = 12.12 "$$

$$2 \times 5 \times 1.05 = 10.50 "$$

Continuation

ABSTRACT OF COST			
1) Making up to Bearings			
Shoulder Stripping excess			
Soil from Shoulder			
(P-20)	185.63 ^{m²}	@ 71.08	Rs = 13194 = 00
2) Maintenance of Road			
Sign — do —			
-20)	0.07 ^{K.M}	@ 1369.60	Rs = 90 = 00
3) Maintenance of 200 m and			
km stones — do —			

Scanned with OKEN Scanner

Scanned with OKEN Scanner