

Agency .. Satish Kr. Singh (Dihri)

Buddhwa to Bari Jaura

Ny. K. 1484 (M. 1414)

Sched. XIV - Trans. No. 134

Trans. No. 134

BIHAR P.W.D.

E.C. R. 1414 under Trans. No. 134 DIVISION

Trans. No. 134

SUB-DIVISION

.. NO. 141484 1404 NO. 14150

Particulars	Details of actual measurement				Contents of area	
	No.	L	B	D		
	4th Year Maintenance					
N/W —	Maint of Rd. From Barriyawa					
	To Bulthwa Barriyawa					
	under head (Agency)					
Agency —	Sattish Kr. Singh					
Agreement No. —	25	SBD	20.21			
Act & D.O. —			18.11.21			

MEASUREMENT

(1) Restoration of Rain cut

Barriyawa Soil

2	1 No	10.00	1.00	.300	6.00
2	2 No	5.60	1.10	.250	6.16
2	1 No	11.40	.90	.300	6.156
2	2 No	12.60	1.00	.300	14.40
2	2 No	9.80	.90	.250	9.80
2	3 No	10.50	1.10	.300	20.79
2	1 No	7.80	1.10	.200	3.43

66.74 m³Limit - 60.75 m³

(2) Make up Barriyawa Shoulder,

Strippy & Extra Soil

2	No	1	10.00	1.0	20.00
2	No	2	11.00	1.00	44.00
2	No	2	15.00	.900	54.00
2	No	2	16.70	.900	60.12
2	No	2	20.00	1.00	80.00
2	No	2	25.00	1.00	100.00

358.12 m³Continuation Limit - 337.50 m³

Sch. XLV-Form No: 134

Particulars	Details of actual measurement				Contents of area
	No.	L	B	D	
(3) Repair of Pot Holes					
Filled with 75 mm					
1 No	1.40	2.00			3.80
3 No	2.10	1.40			8.82
2 No	4.70	1.90			17.86
2 No	9.10	1.20			21.84
2 No	6.00	0.90			10.80
1 No	3.80	1.90			7.22
					70.34 m ²
					70.31 m ²
(4) Patch repair on all ready filled Pot Holes					
20 mm m.s.s					
Qty used 1038.00					
1 item no. - 3					70.34 m ²
					70.31 m ²
(5) Maint of H.P. C					5 No.
(6) Maint of Road Sign					0.11 km
(7) Maint. of 200 M 1/2 K.M Stone					0.14 km
(8) Cutting of Branches of trees & Shrub					2 No.
(9) Cutting of Shrub from Roadway					8 No.

Continuation

Particulars	Details of actual measurement				Contents of area
	No.	L	B	D	
<u>ABSTRACT OF COST</u>					
(1) Restoration of Rain cut.					
do					
60.75 m ³ m de rms P-19					
@ Rs. 386.14/m ³ - Rs.					23458.50
(2) Muck up Borry / Shoulder					
Stripping excess Soil -					
337.50 m ³ m de rms P-19					
@ Rs. 57.36/m ³ - Rs.					19359.00
(3) Repair of Pot Holes					
Filled with 75 mm BM					
do					
70.31 m ³ m de rms P-20					
@ Rs. 211.77/m ³ - Rs.					21921.50
(4) Patch repair Area					
Bituminous Surface -					
70.31 m ³ m de rms P-20					
@ Rs. 247.22/m ³ - Rs.					17385.50
(5) Mant. of H.P.C. -					
500 m de rms P-20					
@ Rs. 1130.67/Each Rs.					5635.50
(6) Mant. of Road Sign -					
0.11 km m de rms P-25					
@ Rs. 1077.82/km - Rs.					1192.00

Continuation

87877.50

Particulars	Details of actual measurement				Contents of area
	No.	L	B	D	
(7) Main 2.5m x 1.5m Stone					
0.14 km wide TMB P-20					
@ Rs 570.89 / km - Ea.					80200
(8) Cutting of Branches of trees					
2.50 m wide TMB P-20					
@ Rs 109.74 / each Ea.					21920
(9) Cutting of shrubs from Roadway					
8.00 m wide TMB P-20					
@ Rs 6.73 / each Ea.					54200
				Ra.	8823000

Add 12.1.4.5.7 + 1.0					1147000
				Ra.	9970000
Less 10.4. Below					9970000
				Ra.	8973000

21/06/21
JER
22/06/21
HE

Material Statement

Etc		94.70 m ³
Stone		7.00 m ³
SS-1		0.019 m ³
Bitumen		0.134 m ³

21/06/21
JER