

[illegible]

D. Reproduction & Rainfall				
5x	10x	0.90x	0.30=	13.5
6x	13x	0.80x	0.80=	18.72
8x	20x	0.60x	0.30=	28.80
7x	9x	0.9x	0.30=	17.01
4x	8x	0.6x	0.30=	5.76
9x	6x	0.9x	0.30=	14.58
3x	12x	0.7x	0.30=	7.56
7x	6x	0.5x	0.30=	6.30
5x	8x	0.9x	0.30=	10.80
4x	9x	0.5x	0.30=	5.40
6x	12x	0.7x	0.30=	19.44
2x	14x	0.9x	0.30=	7.56
7x	9x	0.6x	0.30=	11.84
5x	7x	0.5x	0.30=	5.25

Continuation

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
	3X	12X	0.8X	0.30 =	8.64
					180.66m ³

2) main of Berm shoulder - do

	3X	17X	0.90 =	45.90
	3X	21X	0.80 =	50.40
	4X	14.15X	0.80 =	45.28
	4X	15X	0.70 =	42.00
	4X	21.20X	0.80 =	67.84
	5X	19X	1.00 =	95.00
	5X	7.8X	0.8 =	31.20
	3X	8.1X	0.9 =	21.87
	2X	3.8X	0.7 =	5.32

	5X	6.2X	0.8 =	24.8
	3X	8.8X	0.7 =	7.98
	4X	7.8X	0.8 =	24.96
	2X	8.1X	0.9 =	14.58
	2X	7.6X	0.8 =	12.16
	3X	3.8X	0.8 =	9.12
	5X	2.5X	0.6 =	7.05
	7X	9.0X	0.8 =	50.4
	15X	8.0X	0.8 =	96.0
	2X	8.1X	0.9 =	14.58
	2X	8.5X	0.6 =	10.20
	3X	13.7X	0.8 =	30.78
	2X	12.8X	0.8 =	20.48
	2X	5.7X	0.9 =	10.46
	2X	6.2X	0.8 =	9.92

Continuation

Particulars	Details of actual measurement				Contents of area
	No.	L.	B	D.	
	8x	7.2x	0.7	=	40.32
	9x	8.5x	0.7	=	53.55
	3x	13.6x	0.9	=	36.72
	3x	14.2x	0.8	=	34.08
	3x	10.5x	0.9	=	28.35
					941.30m ²

③ Rebar at Pot holes do-

2x	3.8x	1.72x	0.075	=	0.98
3x	5.4x	2.9x	0.075	=	3.52
4x	2.0x	1.0x	0.075	=	0.60
2x	4.7x	1.9x	0.075	=	1.32
3x	3.2x	1.8x	0.075	=	1.29

2x	3.6x	2.8x	0.075	=	1.50
3x	5.7x	1.6x	0.075	=	2.04
1x	5.2x	2.1x	0.075	=	0.81
					12.06m ³

④ Patch Rebar over BT do-

2x	3.8x	1.72	=	13.07
3x	5.4x	2.9	=	46.98
4x	2.0x	1.0	=	8.0
2x	4.7x	1.9	=	17.86
3x	3.2x	1.8	=	17.28
2x	3.6x	2.8	=	20.16
3x	5.7x	1.6	=	27.36
1x	5.2x	2.1	=	10.92
				161.63m ³

Particulars	Details of measurement				Contents of area
	No.	L	B	D.	
1) Restoration of Raincks					
Qty vide Tm P.N. - (33)					
180.66 @ 379.59 = 68577.00					
2) Repair of Road Shoulder					
Qty vide Tm P.N. - (34)					
941.30 @ 56.81 = 53475.00					
3) Repair of Pot holes					
Qty vide Tm P.N. - (34)					
12.06 @ 10658.14 = 128537.00					

4) Patch Repair of BT-dm					
Qty vide Tm P.N. - (54)					
161.63 @ 253.26 = 40934.00					
5) main of CD works					
Qty vide Tm P.N. - (55)					
3 @ 1102.80 = 3308.00					
6) main of Road signs					
Qty vide Tm P.N. - (55)					
0.40 @ 1054.28 = 422.00					

