

1068 - JAYNAGAR CHOWK TO HARIJAN TOLA

Schedule XLV-Form No. 134

RRSMP

Executive Engineer

DIVISION

R. W. D. WORKS DIVISION

Sitamarhi

Schbar-59

SUB-DIVISION

Shashi Ranson Kumar

Measurement Book

4051

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
3rd on ACPH					
Name of work:- Repairing Of Rock-Loss & Jaggedness channel to Harizan tola.					
Name of Agency - Shree Ram Kumar, Late Ram Kirti Yadav.					
Date of Start - 4/06/25					
Date of Completion - 03-06-2026					
Date of measurement - 25/11/25					
1. Providing and applying Primer Coat With Bitumen emulsion as per specification.					
1 x 30m x 3.75m				= 11.25 m ²	
6 x 30m x 3.80m				= 68.4 m ²	
6 x 30m x 3.90m				= 70.2 m ²	
4 x 30m x 3.75m				= 45.0 m ²	
1 x 20m x 3.75m				= 7.5 m ²	
Widening - 14(4-3.75)				= 3.50 m ²	
8(4.1-3.75)				= 2.80 m ²	
				3042.30 m ²	
2. Providing and applying Green Coat With Bitumen emulsion as per spec.					
TWO times the quantity					
item no. ① Rate - 119 of T.M.B.					
M ₁ -				2 x 3087.30 = 6174.60	

Continuation

$$2 \times 3042.30 = 6084.60 \text{ m}^2$$

Continuation