

MMGSY (S.C.)

Const. with maint of work from Dhamad to
Bandholi Tola Garry Road.

Schedule XLV-Form No. 134

12/23 REVENUE 100
Dhamad 100
DIVISION

TALE SUB-DIVISION

Aggr. Am. Rs. 1,52,30,008.40

MEASUREMENT BOOK

Smt. Sabita Singh

No. 843

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
2nd year Maintenance					
N/W - Dhamad to					
Bandhauri Ga					
Tola Garry					
Agsem - 15/SB/2020-21 (MMGSY-2)					
Agency - Pmti Savita Singh					
D/O/Com - 23/10/2023					

Measurement

1) Restoration of					
Raincut Berms					
with soil					
4 x 15.00 x 0.60 x 0.30				0.30	3.6144
1 x 18.00 x 0.85 x 0.30				0.30	4.80m ³
1 x 30.00 x 0.25 x 0.30				0.30	6.97
1 x 21.00 x 0.80 x 0.30				0.30	13.26
1 x 26.00 x 0.75 x 0.30				0.30	9.00
2 x 11.00 x 0.75 x 0.30				0.30	6.75
4 x 9.00 x 0.80 x 0.30				0.30	5.04
3 x 8.00 x 0.70 x 0.30				0.30	4.75.85
2 x 23.00 x 0.75 x 0.30				0.30	6.60
					4.95
					8.64
					5.04
					10.035

Continuation

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
<u>Abstract of Cost</u>					
1) Restoration of raincut Vide T.M.B Pg-55 Qty - 124.4 m ³ ② ₹ 414.10					₹ 51514.00
2) Making up of Berm shoulder stripping Vide T.M.B Pg-55 Qty 692.45 m ² ② ₹ 56.81					₹ 39338.00
3) Maint. of C/D work (Hume pipe culvert) Vide T.M.B Pg-55 Qty 2 No. ② ₹ 1122.80					₹ 2206.00
4) Maint. of Road Sign Vide T.M.B Pg-55 Qty 2.07 Km					
Continuation					₹ 93058.00

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
				B.F	93058.00
	②	1054.28			2177.00
5) Maint. of 2.00m and Km stone vide T.M.B Pg-55					
Qty - 2.07 Km					
②	651.92				1346.00
6) Cutting of branches of tree and shrub vide T.M.B Pg-55					
Qty - 2 No.					
②	116.73				233.00
7) Cutting of shrub from roadway vide T.M.B Pg-55					
Qty - 10 No.					
②	651				65.00
8) White washing of parapet wall of C.D work vide T.M.D Pg-56					
Qty 23.74 m ²					

Continuation

c. 96819.00

