

Abstract 9 cur

1/1

Restoration of R.C.'s

cuts with soil

P. 32

215:3524³

09

365:25

8

78657:-

2/2

Hard 1 leather shldr

with filly

P. 32

1006.69m²

09

54:37

8

54734

Continuation

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
3/4	Main 1st wing and incl.				
	by 1st wing				
	P. 33				
243.86 m ² @ 9	9	424	33	9	103477
4/3	Repair of Pot hole in				
	1st wing				
	P. 33				
243.86 m ² @ 9	9	300	22	9	73212
5/5	Patch Repair over Pot				
	holes				
	P. 33				
243.86 m ² @ 9	9	284	42	9	69359
6/7	Main 1st H.P. curbs				
	by 1st wing				
	P. 34				
7 m ² @ 9	9	113	64	9	79212
7/9	Main 1st Road Sgn				
	by 1st wing				
	P. 34				
6.00 m ² @ 9	9	1087	63	9	6526
8/10 @	Plaster and app. 20 ft of				
	water covered C. Part				
	P. 34				
80.00 m ² @ 9	9	104	91	9	8393

Continuation

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
7/10 (h) Piv and lapp. 8 lot					
apb. Road 70m					
P-34					
496.20 m ² @ 9		867.77		8	430587.1
					440587.1
10/11 Main 1 = 1.254 km					
P-34					
0.595 km @ 9		749.00		9	446.00
11/12 Cutty & branches 9 line					
P-34					
15 m @ 9		107.48		9	1612.00
12/13 Cutty & branches 9 line					
P-34					
31.01 m @ 9		6.60		9	205.00
13/14 Trinary 9 form of					
walls					
P-35					
2000.32 m ² @ 9		2.20		9	4401.00
14/15 White walling 9 Pers.					
bet wall					
P-35					
46.52 m ² @ 9		16.80		9	782.00
				9	840312.00
on 0.47 v. below				9	3949.00
				9	836363.00
Arava 22/12/25 J.E.					