

कार्यपालक अभियन्ता का कार्यालय
ग्रामीण कार्य विभाग, कार्य प्रमण्डल, सहरसा

पत्रांक 268 /

सहरसा, दिनांक 11-02-25

प्रेषक:-

कार्यपालक अभियन्ता,
ग्रामीण कार्य विभाग,
कार्य प्रमण्डल, सहरसा।

सेवा में,

नोडल पदाधिकारी,
3054 (MR) कोषांग,
बिहार, पटना।

विषय:-

शीर्ष 3054 नई अनुरक्षण नीति-2018 अंतर्गत Initial Rectification and Surface renewal. कराये गये कार्य हेतु अधियाचना के संबंध में।

महाशय,

उपर्युक्त विषयक कहना है कि विहित प्रपत्र में संलग्न विवरणी के अनुसार शीर्ष Mr 3054 New Maintenance Policy-2018. अंतर्गत SH - Narihari Gouth पथ का Initial Rectification and Surface renewal कराये गये कार्य हेतु राशि Rs 18.83124/- (रूपये अठारह लाख तेरासी हजार एक सौ चौबीस मात्र) की आवश्यकता है।

अतः कार्यहित में अनुरोध है कि उक्त अधियाचित Rs 18.83124/- (रूपये अठारह लाख तेरासी हजार एक सौ चौबीस मात्र) उपलब्ध कराने की कृपा की जाय ताकि कराये जा रहे कार्यों का विपत्र भुगतान किया जा सके।

- अनु०:- (1) अधियाचना प्रपत्र
(2) IRI Value Report
(3) Map
(4) प्रमाण-पत्र।

विश्वासभाजन






कार्यपालक अभियन्ता
ग्रा०का०वि०, कार्य प्रमण्डल,
सहरसा

**OFFICE OF THE EXECUTIVE ENGINEER
RWD WORKS DIVISION SAHARSA.**

Name of Scheme:- SH - Narihari Gouth - PACKAGE No- RM/SA/SAH/24/0006, Project ID-20904302099.


Certified that all item wise 100%
Measurement has been taken by me



18/01/25
Junior Engineer
RWD Work section Kahra
Works Division Saharsa

Certified that all item wise 50%
Measurement has been cheked by me


18/1/25
Assistant Engineer
RWD Work Section Kahra
Works Division Saharsa

Certified that all item wise 10%
Measurement has been cheked by me


18/01/25
Executive Engineer
Rural work Department
Works Division Saharsa


18/1/25
T-5

Name of Division : RWD Works Division Saharsa

Rural Works Department
MR NEW MAINTENANCE POLICY-2018, ALLOTMENT & REQUISITION

SL No	Year	Name of Road	Name of Contractor (In English)	Project Id	Administrative Sanction		Agreement Amount: (In Lacs)		Value of IRU (in mm/km)	Thickness of Bitumen Layer (in mm)	Value of Bitumen Content in Percentage	Allotment Received (in Lacs)	Total Expenditure as per MIS (in Lacs)	Value of Measurement (in Lacs)	Current Demand (in Lacs)	Remarks
					Length (in Km)	Amount (in Lacs)	Main Work	Maintenance								
22	2023-24	SH - Northern Gouth	Suresh Sah	20904302099	0.350	28.12000	18.83124	1.73855	2675	25	5%	0.00000	0.00000	18.83124	18.83124	Complete

[Signature]
18/11/23
B.A.O.
RWD Works Division
Saharsa

[Signature]
18/01/25
Executive Engineer
RWD Works Division
Saharsa
18/11/23

Name of Road - SH to Nariyar Goth

Name of Contractor Suresh Sah				Batch Name -RM/SA/SAH/24/0006							
Date	Time	Section	Length	Bumps	Speed	OR	IRI	CATEGOR	Latitude	Longitude	Event
		No.	in km	in mm	Rate	mm/km	mm/km	Y			
14-01-2025	11:53:55	81	0.100	180	10.1	2000	2478	G	25.884344	86.572645	Normal
14-01-2025	11:54:34	81	0.100	270	10.1	2700	3167	G	25.886419	86.572227	Normal
14-01-2025	11:55:00	81	0.100	210	10.1	2100	2577	G	25.886453	86.572229	Normal
14-01-2025	11:55:14	81	0.050	180	10.1	2000	2478	G	25.884375	86.572668	Normal
						Total	10700				
						Average	2675				

$$Y = 0 \cdot X^2 + 0.984 \cdot X + 510.7$$

$$X = 2100$$

$$Y = 2577$$


18/1/25 AC


18/01/25
EC

Analyst:

Name of Customer : Suresh Sah

Name of Work : SH to Nariyar Goth

Road :

Lab Job number :

Date : 14-Jan-25

Section No. : 81

Print

Generate Report and Graph

File : E:\BUMP INDICATOR\Saharsa\14.01.2025.xls, Section No. : 81, Eqn : test

Name of Customer : Suresh Sah, Name of Work/ Road : SH to Nariyar Goth, Lab Job number :

Test Date : 14-Jan-25

Machine No : 403

Road Name : SH to Nariyar Goth

Road Type : (A) ASPHALTIC

Start S No :

Side :

Interval

Start E No :

U/V Range :

Dist Range :

mm/km

Weather :

Equation :

Start Location :

End Location :

Redraw Graph

Map View

U/V
mm/
km

3478

2478

1478

0

0.1

0.2

0.3

0.4

Distance * 1000 m

18/12/25

18/12/25