

कार्यपालक अभियंता का कार्यालय
ग्रामीण कार्य विभाग, कार्य प्रमण्डल, सिवान-1

पत्रांक.... 271 (अबु)

सिवान-1, दिनांक 19/2/25

प्रेषक :- कार्यपालक अभियंता
ग्रामीण कार्य विभाग
कार्य प्रमण्डल, सिवान-1

सेवा में,
नोडल पदाधिकारी (3054)
ग्रामीण कार्य विभाग
बिहार पटना।

विषय :- योजना शीर्ष नई अनुरक्षण नीति 2018 एम0आर0/3054 मद में राशि की अधियाचना के संबंध में।

महाशय,

उपर्युक्त विषयक योजना शीर्ष नई अनुरक्षण नीति 2018 एम0आर0/3054 मद में राशि की अधियाचना विहित प्रपत्र में भर कर अग्रतर कारवाई हेतु समर्पित किया जा रहा

अनुरोध है कि अधियाचित राशि उपलब्ध कराने की कृपा की जाय।

अनु0- 1.विहित प्रपत्र में मॉग विवरणी।

2.Bump Integrator Equipment Report की प्रति।

3.एकरारनामा की छाया प्रति।

विश्वासभाजन

Charu
19/2/25

कार्यपालक अभियंता
ग्रामीण कार्य विभाग
कार्य प्रमण्डल, सिवान-1

Requisition Format for Scheme Head- MR (3054) under Bihar Rural Road Maintenance Policy-2018 (Initial Rectification and Surface Renewal)

Name of Works Division:-RWD, (W) Division, Siwan-1

Sl No	Package No	Name of Road	Project ID as per MIS	Administrative Approval (AA) Letter No & Date	Administrative Approval (AA)		Agreement Amount (In Lakh)		Agreement No & Date	Date of Completion as per Agreement	Actual Date of Completion	Value of IRI (in mm/km)	Thickness of Bitumen Layer (in mm)	Value of Bitumen Content in Percentage	Previous Total Alloted Amount (in Lakhs)	Up-to-date Expenditure as per MIS (in Lakh)	Requisition against work done (in Lakh)	Remarks
					Length (In KM)	amount (In Lakh)	Initial Rectification With Surface Renewal (In Lakh)	5 Year Routine Maintenance (in Lakh)										
1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19
	MR-N/23-24Siwan-1/05	Arjal - Laheji	31406602044	Lt-6153,Dt-05/12/2023	2.6	171.65	132.42304	33.5572	MBD-13/2024-25 17.09.2024	16.09.2025	-	25MM	5	3127	0.000	0.000	128.95623	
	MR-N/23-24Siwan-1/05	L070-Telkhatu Ahir Tola To Puraina (TRACK26)	31406602134	Lt-6153,Dt-05/12/2023	2.5	135.84	98.37426	21.3599	MBD-13/2024-25 17.09.2024	16.09.2025	-	25MM	5	3220	0.000	0.000	93.56234	
Total					5.1	307.49	230.7973	54.9171									222.51857	

1. Signed Hard Copy and Soft copy in excel of recorded IRI is enclose

2. Up to data Physical Progress has been uploaded in MIS

(Signature)
D.A.O
Rural Works Department
Works Division Siwan-1

(Signature)
19/12/25
Executive Engineer
Rural Works Department
Works Division Siwan-1

FORM GFR 19-A

(See Government of India's Decision (I) below Rule-150)

Form of Utilisation Certificate upto the month of Feb-2025

NEW MAINTAINANCE POLICY 2018 (MR3054) MAINTAINANCE

PIU- RWD Works Division Siwan-1

PU- RWD Works Division Siwan-1				
Sl. No.	Name of Scheme	Sanction No. & Date with Amount (in Lakh Rs.)	Amount Received (in Lakh Rs.)	Particulars
1	Construction of Rural Roads under New Maintainance Policy (MR-3054) Maintenance	Previous Allotment	8838.83750	Certified that out of Rs.11487.78749 Lac received during the year 2024-25 in favour of Executive Engineer , R.W.D Bihar Siwan-1 a sum of Rs. 10899.58709 lac. has been utilized for the purpose of New Maintainance Policy (MR-3054) Maintenance Schemes as given in the margin for which it was sanctioned and that the balance of Rs. 588.20040 lac. remaining unutilized at the end of the period under report.
		(Decrease) Lt-68,Dt-06.05.2024	172.59377	
		Lt-69,Dt-06.05.2024	134.13820	
		Lt-72,Dt-29.05.2024	102.6982	
		Lt-94,Dt-29.08.2024	78.90276	
		Lt-103,Dt-01.10.2024	96.48372	
		Lt-105,Dt-01.10.2024	48.75642	
		Lt-108,Dt-21.10.2024	88.49979	
		Lt-115,Dt-29.10.2024	48.85623	
		Lt-118,Dt-06.11.2024	115.90983	
		Lt-122,Dt-20.11.2024	60.53642	
		Lt-129,Dt-29.11.2024	1319.2083	
		Lt-130,Dt-17.12.2024	120.28812	
		Lt-140,Dt-27.12.2024	286.70404	
		Lt-02,Dt-14.01.2025	320.56173	
Total :			11487.78749	

2. Certified that I have satisfied myself that the conditions on which the grants-in-aid was sanctioned have been duly fulfilled/ are being fulfilled and that I have exercised the following checks to see that the money was actually utilized for the purpose for which it was sanctioned.

Kind of Checks exercised :-


- Works have been supervised by Executive Engineer/ Superintending Engineer.
- Periodical inspection has been conducted by Executive Engineer/ Superintending Engineer.
- Construction materials have been tested.
- Measurements have been recorded in the MBs and test check conducted by the Assistant Engineer / Executive Engineer.
- All other codal formalities have been observed.

Physical Progress Achieved:-

- Construction of Road Works.
- Construction of CD Works.



D.A.O
RWD Works Division, Siwan-1



Executive Engineer
RWD Works Division, Siwan-1

Name of Road - L070-Telkhatu Ahir Tola To Puraina (TRACK26)

Date	Time	Section	Length	Bumps	Speed	OR	IRI	CATEGORY	Latitude	Longitude	Event
		No.	in km	in mm	Rate	mm/km	mm/km	ROAD			
19-02-2025	12: 29: 48	121	0.1	360	20.2	3600	3552	G	26.108649	84.382512	Normal
19-02-2025	12: 30: 0	121	0.1	270	10.1	2700	2719	G	26.108783	84.375013	Normal
19-02-2025	12: 51: 0	121	0.1	280	10.1	2800	2806	G	26.109615	84.37598	Normal
19-02-2025	12: 51: 0	121	0.1	340	10.1	3400	3410	G	26.109965	84.379847	Normal
19-02-2025	12: 51: 0	121	0.1	350	10.1	3500	3560	G	26.107058	84.382933	Normal
19-02-2025	12: 51: 0	121	0.1	360	10.1	3600	3625	G	26.105694	84.38298	Normal
19-02-2025	12: 51: 27	121	0.1	320	10.1	3200	3203	G	26.109082	84.375051	Normal
19-02-2025	12: 52: 0	121	0.1	330	10.1	3300	3306	G	26.109712	84.376542	Normal
19-02-2025	12: 52: 2	121	0.1	340	10.1	3400	3433	G	26.109817	84.380831	Normal
19-02-2025	12: 52: 2	121	0.1	290	10.1	2900	2941	G	26.108179	84.382998	Normal
19-02-2025	12: 52: 2	121	0.1	240	10.1	2400	2410	G	26.104572	84.383436	Normal
19-02-2025	12: 52: 37	121	0.1	260	20.2	2600	2679	G	26.109967	84.380325	Normal
19-02-2025	12: 52: 37	121	0.1	260	20.2	2600	2632	G	26.109822	84.379049	Normal
19-02-2025	12: 53: 12	121	0.1	350	20.2	3500	3521	G	26.10945	84.382173	Normal
19-02-2025	12: 53: 12	121	0.1	290	20.2	2900	2957	G	26.109647	84.381796	Normal
19-02-2025	12: 54: 0	121	0.1	330	20.2	3300	3298	G	26.109829	84.377558	Normal
19-02-2025	12: 54: 0	121	0.1	290	20.2	2900	2910	G	26.108711	84.374948	Normal
19-02-2025	12: 54: 23	121	0.1	330	20.2	3300	3298	G	26.108228	84.374233	Normal
19-02-2025	13: 36: 41	121	0.1	290	20.2	2900	2933	G	26.109769	84.381323	Normal
19-02-2025	13: 36: 41	121	0.1	350	10.1	3500	3584	G	26.108624	84.374758	Normal
19-02-2025	13: 37: 0	121	0.1	320	10.1	3200	3254	G	26.10934	84.382333	Normal
19-02-2025	13: 37: 17	121	0.1	380	10.1	3800	3875	G	26.104838	84.383098	Normal
19-02-2025	13: 37: 17	121	0.1	340	10.1	3400	3405	G	26.108599	84.374534	Normal
19-02-2025	13: 37: 17	121	0.1	340	10.1	340	3423	G	26.104489	84.383614	Normal
19-02-2025	13: 38: 0	121	0.1	370	10.1	3700	3759	G	26.103757	84.384232	Normal

Value of IRI - 3220

$$Y = 0 * X^2 + 0.926 * X + 90.84$$

$$X = 2333$$

$$Y = 2251$$

(R) RURAL ROAD

Good	Average	Poor
<4000	4001-5000	>5001

5/8
13/02/25
AE

from
13/2/25
EE
EXECUTIVE ENGINEER
R.W.D. WORKS DIVISION
SIWAN-1

Name of Customer : Balindra Chaudhary
 Name of Work/ Road : L070-Telkhatu Ahir Tola To Pur
 Lab Job number :
 Date : 19-02-2025
 Section No. : 121


Test Date : 19-02-2025 Road Name : L070-Telkhatu Ahir Tola To Pur
 Machine No : 390 Road Type : (R) RURAL ROAD
 Start S No : Side :
 Start E No : Interval
 Weather : UV Range : 1410 To 5000 1000 mm/km
 Start Location : Dist Range : 0 To 2.6 0.1 * 1000 m
 End Location : Equation : $Y = 0 * X^2 + 0.873 * X + 410.1$

Print

Generate Report and Graph

Redraw Graph

Map View



SKB
 15/02/25
 DR

Drawn
 19/2/25
 RB

EXECUTIVE ENGINEER
 A.W.D. WORKS DIVISION
 SIWAN-1