

Mingst (S) Hulasgany (Akshilash Ti)
Diddhi to Pandey Bigha via Hulasgany

Schedule XLV-Form No. 134

Executive Engineer: R. W. D. Warku DIVISION 10 Kari

Assistant Engineer: R. W. D. Warku SUB-DIVISION Konch.
Akshilash Singh

Measurement Book

959

1st year 56 Maintenance

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Name of work: - Const and maint					
of road from Diddhi					
to Pandey Bigha via					
Hulagani under MMSY					
Scheme of MMSY by					
Agency: - SRI Akhilesh Singh					
Ag. NO: - 35/SBN/MMSY (SC) /					
(2022-23)					
Commencement of Date: - 13/07/2022					
Completion of work: - 12/07/2023					
Actual completion date - 10/07/22					
1 Restoration of raincuts					
with S.I.					
$3 \times 13.00 \times 1.00 \times 0.30 = 11.70 m^2$					
$6 \times 10.00 \times 1.00 \times 0.30 = 18.00 m^2$					
$3 \times 11.00 \times 1.00 \times 0.30 = 9.90 m^2$					
					39.60 m ²
2 Making up of Berms/					
Shoulder.					
$8 \times 7.00 \times 1.05 = 58.80 m^2$					
$5 \times 12.00 \times 1.05 = 66.00 m^2$					
$3 \times 11.00 \times 1.05 = 34.65 m^2$					
$4 \times 9.00 \times 1.00 = 36.00 m^2$					
$2 \times 13.00 \times 1.00 = 26.00 m^2$					
					220.45 m ²

Continuation



Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
(3) Repair of potholes filled with 75mm W.B.M. x 1.25					
1x1x0.80 x 0.075 = 0.06 m ²					
(4) patch repair over potholes with cement					
3x4.00 x 0.600 = 7.20 m ²					
2x6.54 x 0.87 = 11.18 m ²					
(5) patch repair m/sq. item ④ = 18.38 m ²					
(5) crack sealing filling of cracks with bit. 785 m					
(6) Repair of concrete pavement					
10x1.00 x 4.45 = 44.5 m ²					
(7) Repair of lat paint					
Sealant - 178.13 m					
(8) maintenance of H.P.C					
2 m/s.					
(9) Maintenance of slabs					
where 1 no					
(10) maintenance of road					
Spand. - 0.975 km					
(11) maintenance of road					
and km stone = 0.975 km					
(12) cutting of branches of trees and shrubs Total = 2 m/s					
(13) Cutting of shrubs from road					
Total - 785 m/s.					

Continuation

Sch. XLV-Form No. 134

[illegible]

Continuation

Abstract of cost estimate provisional

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Name of work - Ditch to provide lighting in the garden					
Agency - Sri P.K. Singh					
Agreement No - 25/522/M/025/CC/2022-23					
Actual date of completion - 10/02/23					
1) Restoration of Rain cut with soil Hypoc 56/					
39.60 m ² @ 1404.06/m ² = 556000					
2) masonry of 20 mm / 20 mm concrete page 56					
22.65 m ² @ 140.28/m ² = 317500					
3) Repair of pot holes 56 with 75 mm concrete page 57					
0.06 m ³ @ 6888.261/m ³ = 41332					
4) patch repair over pot holes with concrete mixed surface page - 57					
18.38 m ² @ 223.64/m ² = 410940					
5) patch repair over 20 mm concrete surface 20 mm concrete page 57					
18.38 m ² @ 249.74/m ² = 458800					
6) cracks sealing filling page 57					
785 m - @ 3.71/m = 2912					
7) Repair of concrete pavement page 57					
4.45 m ² @ 237.64/m ² = 105800					

Continuation 542669

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
		B.F			642669=
(8) Repair & maintenance of					
Joint Sealant.					
		Page - (57)			
178.11 m - @ Rs 24.53/m					Rs 4298=
(9) maintenance of D.H.W.					
		Page - (57)			
2 Nos. @ Rs 1166.58/each					Rs 2333=
(10) maintenance of slope water					
		Page 57			
1 No. @ Rs 2394.96/each					Rs 2395=
(11) maintenance of road					
Sign		Page - (57)			
0.975 km - @ Rs 1104.59/km					Rs 1077=
(12) maintenance of 200m and					
stones.		Page - 57			
0.975 km @ Rs 643.17/km					Rs 6272
(13) Cutting of branches of					
trees and shrubs					
		Page - 57			
2 No @ Rs 113.64/each					Rs 2272
(14) Cutting of shrubs from					
roadway		Page - 57			
785 Nos. @ Rs 6.98/each					Rs 5479=
(15) Trimming of grass and					
weeds.		Page - (58)			
17400 m ² @ Rs 2.33/m ²					Rs 4054=

Continuation

Rs 63159=

Continuation