

Moeh Nadi Full Rahi Terai to Damodri Peth.

MWST-SC

1/300
1/300
Shedule XLV Form No. 134.

Executive Engineer

R. W. D. (W) Division
Darbhanga - 2

DIVISION

Singhware SUB-DIVISION

Sri Makil Ray

Measurement Book

No. 1009

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Abstract of Cost					
(1) Maint. of Rain-water					
vid. H-1, P-63					
= 43.50 ml					
@ A - 404.06/ml					17,577 =
(2) Maint. of Shoulder					
vid. H-2, P-63					
64-243.20 ml					
@ A - 60.28/ml					14,660 =
(3) Maint. of H/Pluvials					
vid. H-3, P-64 = 01 No					
@ A - 1166.58/ea					1167 =
(4) Maint. of Slab Culverts					
vid. H-4, P-64 = 01 No					
@ A - 2394.96/ea					2395 =
(5) Cutting of Tree Branches					
vid. H-5, P-64 = 02 Nos					
@ A - 113.64/ea					227 =
(6) Cutting of shrubs					
vid. H-6, P-64 = 06 Nos					
@ A - 6.98/ea					42 =
(7) White-washing of parapets					
vid. H-7, P-64 = 20.80 ml					
@ A - 16.89/ml					351 =
Total					36,419 = 00

Continuation

Continuation

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Amount of Cost					
(1) Refuse of Refuse					
vidit-1, P-68 = 52.50m					
@ 1/- 404.06/m - 1					21213 =
(2) Maint. of shoulders					
vidit-2, P-68/69 = 288.40m					
@ 1/- 60.28/m - 1					17385 =
(3) Maint. of H/P Culvert					
vidit-3, P-69 = 0.1 Km					
@ 1/- 1166.58/m - 1					1167 =
(4) Maint of Sub Culvert					
vidit-4, P-69 = 0.1 Km					
@ 1/- 2394.96/m - 1					2395
(5) Maint of Road highway					
vidit-5, P-69 = 0.8 to km.					
@ 1/- 1104.58/km - 1					955 =
(6) Maint. of 10m. Stony					
vidit-6, P-69 = 0.8 to km.					
@ 1/- 678.11/km - 1					581 =
(7) Cost of Revolving					
vidit-7, P-69 = 0.2 Km					
@ 1/- 11364/m - 1					227 =
(8) White work of Percept					
vidit-8, P-69 = 20.80m					
Continuation					
@ 1/- 16.89/m - 1					351 =

Continuation