

118.13 m ² @ 57.56 =	6799.20
③ Cutting of branches of trees and shrubs	—
1 No @ 109.81 =	109.81
10% Below	15119.20

ABSTRACT OF COST

① Restoration of Rain cuts	
Beams with Soil do — do	
Qty. TMB. Vide P.No (21)	
J. No - ① 21.186 m ² @ 386.22 =	8182.20
② Making up of Beam Soil :	
Surface level etc do —	
Qty. TMB. Vide P.No - ②1	
1 No - ② 56.32 m ² @ 118.13 =	6658.20
③ Cutting of branches of trees and shrubs do —	
Qty. TMB. Vide P.No - ②1	

Continuation

Particulars	Details of actual measurement			Contents of area
	No.	L.	B.	
J. No (3) 1. No @ 109.81				11000
(4) Maint. of Road Signs da-				
Qty. TMB. Vide P.No - (21)				
S. No - (4) 0. 04 km @ 1078.24				4500
(5) Mairal. of 200m km stone				
Qty. TMB. Vide P.No - (21)				
T.No - (5) 0. 05 km @ 648.44				3300
Total RS =				1502300
Less 10% Below -				150200
Net payable RS =				1352100

[illegible]