

4th year Maintenance bill

Sch. XLV-Form No.134 **68**

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Name of work: Maintn of Road from Talimpur to Bahl Tikam under MGSY NDB- Bries.					
Agency - M/s Uhar Behar Const ^{co} . Pro. Sanjay Kumar					
Agreement No-12 SBD/2019-20					
Date of Start:- 03-09-2019					
Date of Actual Completion- 26-9-2021					
Date of Measurements- 26.06.2025					
(1) Restoration of raincuts with Soil					
L.H.S.	4 Nos	30.00	1.10	0.300	39.60 M ³
	5 Nos	30.00	1.00	0.300	45.00
R.H.S.	6 Nos	20.00	1.10	0.300	39.60
	3 Nos	15.00	1.00	0.300	13.50
					137.70 M ³
(2) Making up of Road & Shoulder					
L.H.S.	2 Nos	30.00	1.05	-	157.50 M ²
	6 Nos	20.00	1.10	-	132.00
	4 Nos	30.00	1.00	-	120.00
R.H.S.	8 Nos	15.00	1.10	-	132.00
	5 Nos	25.00	1.10	-	137.50
	4 Nos	21.50	1.00	-	86.00
					765 M ²
(3) Repair of Potholes 75 mm thick					

Continuation

Sch. XLV-Form No.134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
	8M	2.10	1.50	0.075	1.89M ³
	6M	2.50	1.80	0.075	2.03
	7M	5.80	1.60	0.075	9.87
					8.77M ³
(4) Patch repair over Potholes					
20mm thick.					
Area	8.77	/ 0.075 =			117.17M ²
(5) Patch repair over bit.					
Surface					
6M	2.50	1.80	-		27M ²
8M	2.10	1.60	-		26.88
4M	3.00	1.20	-		14.40
5M	3.15	1.20	-		48.70
					117.18M ²
(6) Maint. of CD works.	04M				
(7) Maint. of Road signs	0.26M				
(8) Maint. of 200M					
KM Stone	-	-	-		0.31KM
(9) cutting of branches of					
Tree	-	-	-		04M
(10) cutting of Shrub from					
roadway	-	-	-		17M
(11) Trimming of grass					
over					
2	2	12.00	0.250		9.68M
(12) White washing of Parapet					
Some Apr 9 3rd yr Maint.					103.92M

Continuation

26/04/25
J.E.

Sch. XLV-Form No.134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Abstract of cost:					
(1) Restoration of rainwater soil					
137.70M ³		Vide TMB			
		P-68			
@ 378.32/M ³ - R					52095.00
(2) Making up of berms & shoulder					
765M ³		Vide TMB			
		P-68			
@ 58.42/M ² - R					44691.00
(3) Repair of Potholes 75 mm thick					
8.79M ²		Vide TMB			
		P-69			
@ 1114.79/M ² - B					9793.00
(4) Patch repair over Potholes 20mm thick					
117.19M ²		Vide TMB			
		P-69			
@ 305.42/M ² - B					35792.00
(5) Patch repair over bit. Surface					
117.18M ²		Vide TMB			
		P-69			
@ 322.31/M ² - R					37768.00
(6) Maint. of H.P culvert					
0.41M		Vide TMB			
		P-69			
@ 1147.67/M - B					4439.00
(7) Maint. of Road sign					
0.26KM		Vide TMB			
		P-69			
@ 1066.50/KM - B					277.00
					R 272968.00

Continuation

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
				BRR 2	72768.00
(8) Maint. of 200M R.M.					
0.31KM			Vide TMB		
			P-69		
			@ 1651.05/KM - R		202.00
(9) cutting of branches of trees.					
4NM @ 17			105-39/MH - R		422.00
(10) cutting of shrubs from Roadways					
17NM @ 12			6247/MH - R		110.00
(11) Trimming of grass & weeds					
9.68M ²			@ 216/M ² - R		212.00
(12) whole washing of parapet wall.					
103.92M ²			Vide TMB		
			P-69		
			@ 1654/M ² - R		1739.00
					R 2,75,492.00
Less 0.05% b.e/o work				R	138.00
				P	2,75,354.00
26/04/25 T.E					

Continuation