

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Name of work:- Maint. of road - from					
	LO31	middle school Badanti yadav			
	-to	Committee Tola.			
Agency:-	Ujjawal Shakti Const. Pvt. Ltd.				
Agg. Nos:-	1885 BD/2021-22.				
Actual completion Date:-	16/01/2023.				
<u>Record Entry</u>					
1.	Restoration of				
	rain cuts - do -				
	12X	6.45	11.12	0.30	$= 26.01m^3$
	11X	4.72	11.19	0.30	$= 18.54m^3$
					$44.55m^3$
2.	Making up of				
	earthen shoulder - do -				
	2X9	5.3	2X1.38		$= 132.15m^2$
	2X12	4.68	2X1.25		$= 140.40m^2$
	2X10	4.85	2X1.32		$= 128.04m^2$
					$400.59m^2$
3.	patch repairs over				
	bituminous surface - do -				
	7X	3.11	0.98		$= 21.33m^3$
	6X	2.66	0.88		$= 14.04m^3$
					$35.37m^3$

Continuation

Abstract of cost

44

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
(1/1) Restoration of raincuts -do-					
44.55m ³ vide T.m. B p. (42)					
RS. 396.73/m ³ — RS. 17674.00					
(2/2) Maint. of earthen Shoulder -do-					
400.59m ² vide T.m. B p. (42)					
RS. 59.87/m ² — RS. 23983.00					
(3/5) patch repair with bituminous surface -do-					
35.37m ² vide T.m. B p. (42)					
RS. 306.14/m ² — RS. 10828.00					
(4/5) Maint. of road signs -do-					
0.61km vide T.m. B p. (43)					
RS. 1077.81/km — RS. 657.00					
(5/10) Maint. of 200m of km Stone -do-					
1.22km vide T.m. B p. (43)					
RS. 707.26/km — RS. 863.00					
(6/11) Trimming of grass & weeds -do-					
828.00m ² vide T.m. B p. (43)					
RS. 2.24/m ² — RS. 1855.00					
(7/11) Maint. of trees by road sides -do-					

Continuation

Continuation