

MEASUREMENT

Item No - 1/1

Restoration of Raincuts-24

$$3 \times 20.00 \times 1.49 \times 0.70$$
$$= 62.58 \text{ m}^3$$

Continuation

Sch.XLV-Form No. 134

Particulars	Details of actual measure				Contents of area
	No.	L.	B.	D.	
Abstract of Cost —					
Item No — 1/1					
Restoration of raincuts — 24					
Room TMB PNO — 24					
					Qty = 62.58003
					@ Rs. 466.17/m ³
					= Rs. 29173 ~
Item No — 2/2					
Making up of beams/					
Shoulders — 25					
Room TMB PNO — 25					
					Qty = 248.85002
					@ Rs. 70.08/m ²
					= Rs. 17439 ~
Item No — 3/3					
Maintenance of bitumen					
MSS — 25 — 25					
Room TMB PNO					
					Qty = 29.56002
					@ Rs. 743.50/m ²
					= Rs. 21978 ~
Item No — 4/5					
Maintenance of HPC					
Room TMB PNO — 25					
					Qty = 1110
					@ Rs. 1529.29/m ¹
					= Rs. 1529 ~

Continuation

Sch.XLV-Form No. 134

Particulars	Details of actual measure				Contents of area
	No.	L.	B.	D.	
2km No - 5/6					
Maintenance of box culvert					
Room TMS PNO - 25 -					
				Qty = 1 NO	
				@ Rs. 3105.14/NO	
				= Rs. 3105.14	
2km No - 6/8 - 25 -					
Maintenance of room and					
km stones - 25					
Room TMS PNO - (25)					
				Qty = 1.26 km	
				@ Rs. 1022.26/km	
				= Rs. 1288.05	
				Rs. 74512	
Add for GST @ 18% =				13412	
Add for LC @ 1% =				745	
Add for C.F. =				762	
				Rs. 89431	
Less for below @ 0.10% =				89.43	
Bay Rs.				89342	

Continuation