

AA vide letter no - 310370 (31030) 4515 - 01-15/2025 - 73 /
Details of AA
 Dated 17/01/25

cost of Initial Rectification & Surface Renewal	£ 143.210 lakhs
6 year operation & management cost	£ 28.816 lakhs
Emergent & Price Adjusted cost	£ 28.804 lakhs
Contingency & Administrative fund	£ 5.591 lakhs
Total	£ 203.421 lakhs

Details of TS

Construction cost	£ 143.211 lakhs
6 year operation & management cost	£ 27.750 lakhs
Contingency cost @ 1%	£ 1.710 lakhs
Administrative fund @ 2.5%	£ 3.847 lakhs
Total	£ 176.518 lakhs

TS No.....dt.....
 Ref. S.E. Letter No.....203.....dt.....03.03.25
 Technical Sanction Accorded for Rs. 176.518...
 (Rupees...one crore, seventy...two...
 fifty one...thousand...six hundred...) only.

Technical Sanction does not mean sanction of rate. Instruction given in technical note should be followed strictly.

A.E. *[Signature]* 05.03.25
 Tec.Secy. *[Signature]*
 C.E.-4 *[Signature]*