

Details of AA

AA vide letter no - प्र.प्र. (प्र.प्र.) 4515-01-80/2025
Dated 14/02/25

357/

Cost of Initial Rectification &
Surface Renewal - 135.322 lacs

Exp operation & management cost - 16.829 lacs

Emergent & Price Adjustment
cost - 22.823 lacs

Contingency & Administrative fund - 4.945 lacs

Total - 179.919 lacs.

Details of TS

Construction Cost - 137.197 lacs

Exp operation & management
cost - 16.440 lacs

Contingency Cost @ 1% - 1.536 lacs.

Administrative fund @ 2.25% - 3.457 lacs.

Total - 158.63 lacs.

~~T.S. No. dt.
Ref. SE letter No. 203 dt. 03.03.25
Technically Sanctioned
Approved for Rs. 158.63 lac
Rupees one crore fifty eight lac
sixty thousand
(Only
sanction work & 6 Years Maintenance~~

E. Tec. Secy. C.E-4

T.S. No. dt.
Ref. SE letter No. 203 dt. 03.03.25
Technically Sanction Accorded for Rs. 158.63,000/-
(Rupees one crore fifty eight lac sixty
three thousand) Only
Technical Sanction does not mean sanction
of rate. Instruction given in technical note
should be followed strictly
05.03.25
A.E. E. Tec. Secy. C.E-4