

Mukhya Mantri Gramin Setu Yojna(MGSY)

AGREEMENT NUMBER :- 06/CMBD1

:- 06/CMBD/MGSY/2025-26

NAME OF WORK

:- (1) HL RCC Bridge in Panchayat Chanki gram madhwan tola

(2) Panchayat Sotwa ke charnadh me pul ka nirman

(3) HL RCC Bridge in Nokha nagar praishad ke gram dharupur me chosa nahar per asathit pul ka jinordwar Block Nokha

Under (MGSY)

NAME OF CONTRACTOR

:- Jai Mata Dee And Maa Sita Construction

Vill :- Pachpokhari, PS-Baghila Nokha Rohtas Pin Code-802217,

(Registration No.1240478/1st Class) Mob.No.

Email ID-

:-

Estimated Cost :-

Construction Cost (in lakh).

:- Rs. 1023.44307

Maintenance Cost. (in lakh)

RS. 7.05099

Total Cost of Project(in lakh) :-

RS. 1030.49406

Agreement Amount :-

Construction Cost (in lakh).

:- Rs. 907.99869

Maintenance Cost. (in lakh)

RS. 6.25564

Total Cost of Project(in lakh) :- RS.

914.25433

Date of work Start

:- 05.07.2025

Date of Completion

:- 04. 07. 2027

Defect Liability Period

:- 5 Years (from LOA)

Rate Quoted

11.28 % Below

Pan No.	AWMPK9580H
GST No.	10AWMPK9580H1ZA
Registration No/Date and Class	1240478/ 16.11.2024 Class Ist



ग्रामीण कार्य विभाग

Rural Works Department, Govt of Bihar


JAI MATA DEE AND MAA SITA CONSTRUCTION

Janja Kimis

Proprietor

Executive Engineer

Work Division Sesaram-2





This agreement made the.

Rural Works Department, Works Division Sasaram-2 of the one part and Jai Mata Dee and Maa Sita Construction(Prop. Sanjay Kumar) Vill-Pachpokhari, PS- Baghila, Nokha Rohtas Bihar (Bid ID:-615248)Whereas the Employer is desirous that the Contractor execute Construction of Setu ,Under the Package No:- Head SETU/MGSY/ 24-25/Sasaram-2/03-2025 Tender ID-140491_1 and thereafter undertake routine maintenance for Six years and the Employer has accepted the Bid by the Contractor for the execution and completion of such works and the remedying of any defects and routine maintenance therein, at the cost of Rupees 914.25433 (Rupees Nine Crore Fourteen lakh Twenty Five Thousand Four Hundred Thirty Three only)

Executive Engineer Work Division Sasaram-2