

Name of Road + Target ya Panchayati Mukhaya path,
Pokhara Baghi to Chakya Panchayati

Schedule XLV-Form No. 134

NDB Bricks-

DIVISION

14/11

SUB-DIVISION

796

MEASUREMENT BOOK

M/S Shiv Shankar Construction

3rd year Maintenance

35

Sch. XLV—Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Name of work - Maintenance of road from taraiya Panapur Mukhya path Pokhrara Bag to chakia Pmudy Path.					
Agency - M/s chivshakti construction					
D.O.S - 22/10/2020					
D.O.C - 21/10/2021					
Actual date of completion - 16/03/22					
Date of entry - 13/03/25					
Recons entry					
① Restoration of raincut					
20 - 20 -					
5 x 4.25 x 1.20 x 0.30 = 7.65 m ³					
6 x 6.50 x 1.30 x 0.30 = 15.21 m ³					
4 x 8.65 x 1.25 x 0.30 = 12.98 m ³					
6 x 7.0 x 1.20 x 0.30 = 15.12 m ³					
4 x 5.0 x 1.30 x 0.30 = 7.80 m ³					
7 x 8.0 x 1.25 x 0.30 = 21.0 m ³					
4 x 8.0 x 1.20 x 0.30 = 11.52 m ³					
Qty. Total = 91.28 m ³					
② Maintenance of earthwork					
Shoulder - 20 -					
6 x 12.0 x 1.30 = 93.60 m ³					
4 x 8.0 x 1.25 = 40.0 m ³					
5 x 11.0 x 1.20 = 66.0 m ³					
7 x 6.0 x 1.20 = 50.40 m ³					

Continuation

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
④ Maintenance of road sign.					
		1.29	0.15		= 0.19 km
⑤ cutting of branches of tree					
					= 2 No
⑥ Providing & laying hot applied thermoplastic compound —					
		2 x 2.9	30.0	0.10	= 174.0 m ²
		2 x 1.4	20.0	0.10	= 84.0 m ²
		Total =			258.0 m ²
⑦ Maintenance of already planted tree					
					= 90 No
⑧ white washing of Paraphet do. do.					
					2 21 m ²
					15.25
					13.92
					30
Abstract of work					
① Restoration of rain gut — do — do — exp					
		91.25 m ³	vide TMB, P-35		
		@ 400.74/m ³	=	36565.20	
② Maintenance of earthen shoulder — do —					
		349.25 m ²	vide TMB, P-35		

Continuation

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
	@	59.52/m ²			B 20787.2
③ Patch repair on pot hole		do	do		
61.15 mt vilt TMB, P-36	@	294.18/m ²			B 17989200
④ Maintenance of bituminous mix seal surface - do.					
62.40 mt vilt TMB, P-36	@	312.94/m ²			B 1952720
⑤ Maintenance of c.c./bitumen P/R culvert					
1 No. vilt TMB, P-36	@	1173.24/m ²			B 1173200
⑥ Maintenance of culverts		do	do		
1 No. vilt TMB, P-36	@	2417.10/m ²			B 2417200
⑦ Maintenance of Road BM		do	do		
0.19 km vilt TMB, P-36	@	1118.49			B 213200
⑧ Cutting of branches of trees - do.					
2 Nos vilt TMB, P-36	@	113.88/m ²			B 22820
⑨ Pr.s laying not applied Bituminous thermoplastic Paint					

Continuation

C to 98899.

[illegible]

⑪ while working at Parapur
→ 20 - Dec

17/3/24

17/3/20
J-85

Continuation