

कार्यपालक अभियंता का कार्यालय
ग्रामीण कार्य विभाग, कार्य प्रमण्डल, बेनीपुर

पत्रांक- ८३७

दिनांक- 5/6/25

प्रेषक,

कार्यपालक अभियंता,
ग्रामीण कार्य विभाग,
कार्य प्रमण्डल, बेनीपुर।

सेवा में,

नोडल पदाधिकारी,
3054 एम.आर. कोषांग,
ग्रामीण कार्य विभाग, बिहार, पटना।

विषय- MR (3054) under New Maintenance Policy- 2018 के क्रियान्वित पथों के विपत्र भुगतान हेतु अधियाचना के संबंध में।

प्रसंग- भवदीय पत्रांक 113 अनु0 दिनांक 10.01.2020

महाशय,

उपर्युक्त विषयक प्रासंगिक पत्र के संबंध में कहना है कि कार्यप्रमण्डल बेनीपुर अन्तर्गत MR (3054) under New Maintenance Policy- 2018 के क्रियान्वित पथों में से कार्य पूर्ण कराये गये पथ के विपत्र भुगतान हेतु विहित प्रपत्र में अधियाचना तैयार कर आपके आवश्यक कार्यार्थ समर्पित की जाती है।

सूचनार्थ एवं आवश्यक कार्रवाई हेतु समर्पित।

अनु0- 1. अधियाचना विहित प्रपत्र में।

2. Recorder IRI की प्रतिहस्ताक्षरित प्रति।

विश्वासभाजन

कार्यपालक अभियंता,
ग्रामीण कार्य विभाग,
कार्य प्रमण्डल बेनीपुर

Pureh
5/6/25

IMP
5/6/25

Form GFR 19- A

(See Government of India's Decision (I) below Rule - 150)
Form of Utilization Certificate upto the month 29.05.2025
New Maintenance Policy 2018

Sl. No.	Name of Scheme	Sanction No. & Date with Amount (in lacs)	Amount Received (in lacs)	Particulars
1	New Maintenance Policy 2018	Letter No 56 Dated 12.08.2020 Letter No 86 Dated 11.12.2020	Rs 30.80000 Vide Letter No :- 45 Dated 27.05.2025	Certified that out of RS 2551.07196 lacs of grants in aid sanctioned during the Years up to 2024-25 in favour of Executive Engineer, RWD Works Division Benipur under this Department, a sum of Rs 2519.84266 lacs has been utilized for the purpose of New_MR Scheme remaining 0.42930 unutilized at the end of the period under report.
		Total :	30.80000	


Certified and verified myself that the conditions on which the grants in aid was sanctioned have been duly fulfilled / are being fulfilled and that I have exercised the following checks to see that the money was actually utilized for the purpose for which it was sanctioned.

Kinds of Checks exercised :-

- Works have been supervised by Executive Engineer/ Superintending Engineer.
- Periodical inspection has been conducted by Executive Engineer/ Superintending Engineer.
- Construction material have been tested.
- Measurements have been recorded in the MBs and test check conducted by the Assistant Engineer/Executive Engineer.
- All other codal formalities have been observed.

Physical Progress achieved :-

- Construction of Road works.
- Construction of CD works


D.A.O.
RWD works Division
Benipur


Executive Engineer
RWD works Division
Benipur


5/6/2025

Requisition Format for Scheme Head - MR (3054) Under Bihar Rural Road maintenance Policy 2018 (Initial Rectification and Surface Renewal)																		
Name of Division : BENIPUR																		
Sl.No	Package no.	Name of Road	Project ID as per MIS	Administrative Approval (AA) Letter No. & Date	Administrative Approval (AA)		Agreement Amount (in Lac)		Agreement No. & Date	Date of Completion as per Agreement	Actual Date of Completion	Value of IRI (in mm/km)	Thickness of Bitumen Layer (in mm)	Value of Bitumen Content in percent age	Previous Total Allotted Amount (I Lac)	up to date expenditure as per MIS (in Lac)	Requisition Against GST Claim (in lac)	Remarks
					Length (In Km)	Amount (in Lac)	Initial Rectification with Surface Renewal (in lac)	5 years Routine Maintenance (In lac)										
1	RM/DA/BEN/23/00 01	L032-L034 Khabna to Sajjanpura (VR32)	31909402056	1447 / 28.02.2023	1.900	131.33	88.23762	27.8763	07/MBD/2024-25 / 25.09.2023	24.06.2024	15.03.2024	2559.10	25mm	5%	87.53113	79.83716	7.69397	Road Complete

[Signature]
5/6/25

Divisional Accounts Officer
RWD Works Division
BENIPUR

[Signature]
5/6/25

Executive Engineer
RWD Works Division
BENIPUR

[Signature]
5/6/25

NAME OF ROAD-L032-L034 Khabna to Sajjanpura (VR32)

NAME OF CONTRACTOR-RANJEET KUMAR RAUT

NAME OF CONTRACTOR-RANJEET KUMAR RAUT											
Date	Time	Section	Length in km	Bumps in mm	Speed Rate	OR mm/km	IRI mm/km	EGORY	Latitude	ongitude	Event
		No.						ROAD			
17/2/24	13:40:0	66	0.1	190	0	1900	1799	G	26.25142	86.25251	Normal
17/2/24	13:40:33	66	0.1	230	30.3	2300	2125	G	26.2543	86.25423	Normal
17/2/24	13:40:33	66	0.1	290	30.3	2900	2615	G	26.2532	86.2547	Normal
17/2/24	13:41:0	66	0.1	320	30.3	3200	2860	G	26.2507	86.25793	Normal
17/2/24	13:41:8	66	0.1	250	30.3	2500	2288	G	26.2668	86.25974	Normal
17/2/24	13:41:8	66	0.1	320	30.3	3200	2860	G	26.30073	86.26384	Normal
17/2/24	13:41:8	66	0.1	270	30.3	2700	2452	G	26.30737	86.26573	Normal
17/2/24	13:41:43	66	0.1	260	30.3	2600	2370	G	26.32387	86.26628	Curve
17/2/24	13:42:0	66	0.1	300	30.3	3000	2696	G	26.3401	86.26822	Normal
17/2/24	13:42:0	66	0.1	320	30.3	3200	2860	G	26.34713	86.26983	Normal
17/2/24	13:45:15	66	0.1	330	0	3300	2941	G	26.35418	86.27368	Normal
17/2/24	13:45:15	66	0.1	290	30.3	2900	2615	G	26.3538	86.27056	Normal
17/2/24	13:45:15	66	0.1	340	30.3	3400	3023	G	26.35402	86.27064	Normal
17/2/24	13:45:15	66	0.1	270	30.3	2700	2452	G	26.35435	86.27065	Normal
17/2/24	13:45:50	66	0.1	300	30.3	3000	2696	G	26.35463	86.2707	Normal
17/2/24	13:46:0	66	0.1	340	30.3	3400	3023	G	26.35498	86.27073	Normal
17/2/24	13:46:0	66	0.1	230	30.3	2300	2125	G	26.35528	86.27077	Normal
17/2/24	13:46:26	66	0.1	220	30.3	2200	2044	G	26.35753	86.27269	Normal
17/2/24	13:46:26	66	0.1	310	30.3	3100	2778	G	26.3572	86.27294	Normal
TOTAL LENGTH			1.9	5380	515.1	5380	48622				
			AVERAGE IRI		2559.1						

Y = 0 * X ^ 2 + 0.816 * X + 249

X = 3100

Y = 2778

(R) RURAL ROAD

Good <4000

Average 4001-5000

Poor >5001

Y = 0 * X ^ 2 + 0.816 * X + 249
X = 3100
Y = 2778


(R) RURAL ROAD
Good Average Poor
<4000 4001-5000 >5001

[Signature]

EXECUTIVE ENGINEER
RURAL WORKS DEPARTMENT
WORKS DIVISION, BENIPUR

[Signature]
05.06.2018

RURAL WORKS DEPARTMENT WORKS DIVISION, BENIPUR



spw
05-06-2024

[Signature]
EXECUTIVE ENGINEER
RURAL WORKS DEPARTMENT
WORKS DIVISION, BENIPUR