

(MAGSY NEWS)

M.B.No-3177

Schedule XLV-Form No 134

ਮਾਮਲਾ ਨੰਬਰ-ਸਬ-ਸਮਾਜ-ਸੁਰਕਸ਼ਾ-ਸੇਵਾ-ਸਮਾਜ

M.No-32880/2003-20

ਕੋਰਟ ਓਫ਼ ਫਿਰਮ ਫਿਰਮ ਫਿਰਮ ਫਿਰਮ  
DIVISION

ਸ਼ਾਇਦ ਮਾਮਲਾ ਨੰਬਰ-32880/2003-20

ਸਬ-ਸਮਾਜ-ਸੁਰਕਸ਼ਾ-ਸੇਵਾ-ਸਮਾਜ  
SUB-DIVISION

ਮਾਮਲਾ ਨੰਬਰ

MEASUREMENT BOOK

M.B.No-3177



# 5th year Maintenance Bill

71

Sch. XLV—Form No. 134

| Particulars                      | Details of actual measurement |    |    |    | Contents of area |
|----------------------------------|-------------------------------|----|----|----|------------------|
|                                  | No.                           | L. | B. | D. |                  |
| N/w: Gauram Bakkunda me phabanth |                               |    |    |    |                  |
| Singh Kaghun Singh Nigbi         |                               |    |    |    |                  |
| Kaghun kote hua Bisunpura        |                               |    |    |    |                  |
| Samra tuk                        |                               |    |    |    |                  |
| Agony: Sh. Rambabu Kumar         |                               |    |    |    |                  |
| Agmt NO: 32/SBD/19-20            |                               |    |    |    |                  |
| D.O.C (att): 20/05/20            |                               |    |    |    |                  |

Revised entry:

① Restoration of Reincut/Burns with soil/mann - -

10 x 7.50 x 0.60 x 0.30 = 13.50

8 x 5.10 x 0.55 x 0.30 = 6.60

11 x 8.75 x 0.60 x 0.30 = 17.32

6 x 4.75 x 0.60 x 0.30 = 5.13

18 x 3.70 x 0.55 x 0.30 = 10.99

20 x 2.50 x 0.60 x 0.30 = 9.00

15 x 3.10 x 0.60 x 0.30 = 8.10

11 x 6.20 x 0.55 x 0.30 = 11.25

8 x 5.10 x 0.60 x 0.30 = 7.20

13 x 4.10 x 0.55 x 0.30 = 8.91

10 x 5.25 x 0.60 x 0.30 = 9.45

7 x 4.10 x 0.55 x 0.30 = 4.62

5 x 8.10 x 0.55 x 0.30 = 6.60

T. 44 = 118.67

lined = 117.55

② Making up of Burns/shoulders striping ex - -

Continuation

| Particulars       | Details of actual measurement |    |    |    | Contents of area |
|-------------------|-------------------------------|----|----|----|------------------|
|                   | No.                           | L. | B. | D. |                  |
| 10 x 3.90 x 1.125 |                               |    |    |    | 43.8875          |
| 5 x 4.50 x 1.125  |                               |    |    |    | 25.31            |
| 8 x 4.15 x 1.125  |                               |    |    |    | 36.40            |
| 11 x 3.00 x 1.125 |                               |    |    |    | 37.125           |
| 8 x 4.25 x 1.125  |                               |    |    |    | 38.25            |
| 5 x 2.75 x 1.125  |                               |    |    |    | 15.47            |
| 7 x 3.75 x 1.125  |                               |    |    |    | 29.53            |
| 10 x 4.15 x 1.125 |                               |    |    |    | 46.69            |
| 6 x 5.10 x 1.125  |                               |    |    |    | 33.75            |
|                   |                               |    |    |    | T. Qty. = 305.80 |
|                   |                               |    |    |    | Net - 298.69 m   |

③ Repair of Potholes filled with  
75m WBM x 1.5

|                 |  |  |  |  |                  |
|-----------------|--|--|--|--|------------------|
| 6 x 1.25 x 1.20 |  |  |  |  | 7.25             |
| 5 x 1.30 x 1.25 |  |  |  |  | 8.125            |
| 5 x 2.00 x 1.15 |  |  |  |  | 11.50            |
| 1 x 4.25 x 0.80 |  |  |  |  | 3.80             |
| 2 x 5.25 x 1.00 |  |  |  |  | 10.50            |
| 1 x 6.25 x 0.75 |  |  |  |  | 4.69             |
| 1 x 7.50 x 0.80 |  |  |  |  | 6.00             |
| 3 x 2.75 x 1.00 |  |  |  |  | 8.25             |
| 5 x 1.30 x 1.50 |  |  |  |  | 9.75             |
|                 |  |  |  |  | T. Qty. = 72.365 |
|                 |  |  |  |  | Net - 69.44 m    |

④ Patch repair over potholes  
filled with - -

Continuation



| Particulars                                         | Details of actual measurement |    |    |    | Contents of area     |
|-----------------------------------------------------|-------------------------------|----|----|----|----------------------|
|                                                     | No.                           | L. | B. | D. |                      |
| Qty same as item (3)                                |                               |    |    |    |                      |
| B/F TMB/p-72                                        |                               |    |    |    | 69.14m <sup>2</sup>  |
| (5) Patch repair over Bituminous surface --         |                               |    |    |    |                      |
| Qty same as item (3)                                |                               |    |    |    |                      |
| B/F TMB/p-72                                        |                               |    |    |    | 69.14m <sup>2</sup>  |
| (7) Maintenance of CD work --                       |                               |    |    |    |                      |
| 2x1.10                                              |                               |    |    |    | 2.10                 |
| (9) Maintenance of road signs                       |                               |    |    |    |                      |
| 0.19x1                                              |                               |    |    |    | 0.19km               |
| (10) Maintenance of road signs                      |                               |    |    |    |                      |
| 0.31x1                                              |                               |    |    |    | 0.31km               |
| (11) P/L hot applied thermoplastic compound 2.5m -- |                               |    |    |    |                      |
| Qty same as B/F                                     |                               |    |    |    |                      |
| TMB/p-43 (30/13)                                    |                               |    |    |    | 118.10m <sup>2</sup> |
| TMB/p-43 (50/10)                                    |                               |    |    |    | 140.10m <sup>2</sup> |
| T.Qty                                               |                               |    |    |    | 258.10m <sup>2</sup> |
| (10/13) White washing of parapet wall --            |                               |    |    |    |                      |
| Qty B/F TMB P-70 (10)                               |                               |    |    |    | 42.10m <sup>2</sup>  |

Continuation

2-6-25  
 J.E.

Continuation



| Particulars                       | Details of actual measurement |    |    |    | Contents of area |
|-----------------------------------|-------------------------------|----|----|----|------------------|
|                                   | No.                           | L. | B. | D. |                  |
| 5. Patch repair over bitumi       |                               |    |    |    |                  |
| Qty B/F TMB/P-73.                 |                               |    |    |    |                  |
| 69.14 m <sup>2</sup> @ 326.95     |                               |    |    |    | = 22605 = 0      |
| 6/7. Maintenance of c. & u. work  |                               |    |    |    |                  |
| Qty B/F TMB/P-73.                 |                               |    |    |    |                  |
| 2.10 @ 1109.67                    |                               |    |    |    | = 22192 = 0      |
| 7/9. Maintenance of Road -        |                               |    |    |    |                  |
| Qty B/F TMB/P-73.                 |                               |    |    |    |                  |
| 0.19 km @ 1066.50                 |                               |    |    |    | = 203 = 0        |
| 8/10. Maintenance of 200m -       |                               |    |    |    |                  |
| Qty B/F TMB/P-73                  |                               |    |    |    |                  |
| 0.31 km @ 641.62                  |                               |    |    |    | = 199 = 0        |
| 9/12. P/2 ho-uppling -            |                               |    |    |    |                  |
| Qty B/F TMB/P-73                  |                               |    |    |    |                  |
| 10/13. White washing -            |                               |    |    |    |                  |
| Qty B/F TMB/P-73.                 |                               |    |    |    |                  |
| 42.10 m <sup>2</sup> @ 16.54      |                               |    |    |    | = 695 = 0        |
| 11.(i) Cutting of Branches -      |                               |    |    |    |                  |
| Qty B/F TMB/P-74.                 |                               |    |    |    |                  |
| 2.10 @ 105.39                     |                               |    |    |    | = 211 = 0        |
| 11.(ii) Cutting of shrubs -       |                               |    |    |    |                  |
| Qty B/F TMB/P-74.                 |                               |    |    |    |                  |
| 6.10 @ 6.42                       |                               |    |    |    | = 39 = 0         |
| 11.(iii) Trimming of grass dump - |                               |    |    |    |                  |
| Qty B/F TMB/P-74                  |                               |    |    |    |                  |
| 15.10 m <sup>2</sup> @ 2.16       |                               |    |    |    | = 32 = 0         |
|                                   |                               |    |    |    | 371636 = 0       |
| Less 10% below                    |                               |    |    |    | (-) 37164 = 0    |

Continuation

Total = 334412 = 0

Prepared  
2-6-25  
S.E.

checked  
02/06/25  
S.E.

| Particulars                  | Details of actual measurement |    |    |    | Contents of area      |
|------------------------------|-------------------------------|----|----|----|-----------------------|
|                              | No.                           | L. | B. | D. |                       |
| <u>Natural Material</u>      |                               |    |    |    |                       |
| (i) Earthwork —              |                               |    |    |    | 163.10 m <sup>3</sup> |
| (ii) Stonework —             |                               |    |    |    | 45.10 m <sup>3</sup>  |
| (iii) Stone dust —           |                               |    |    |    | 10.50 m <sup>3</sup>  |
| (iv) Stone chips —           |                               |    |    |    | 4.10 m <sup>3</sup>   |
| (v) Bitumen emulsion (4.1) — |                               |    |    |    | 0.04 MT               |
| (vi) Bitumen S-40 —          |                               |    |    |    | 0.15 MT               |

Prepared

2-6-25  
J. S.

Checked  
22/06/25  
H. S.

C. S.

22/06/25  
EE

Continuation