

4th year maintenance
Sch. XLV-Form No. 134 74

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Name of road -					
Agency →					
D.O. Actual →					
Completion					

Recordentry

1. Restoration of raincut

$$1 \times 35.0 \times 1.05 \times 0.30 = 26.77 \text{ m}^3$$

$$1 \times 65.0 \times 0.95 \times 0.30 = 18.52 \text{ m}^3$$

$$1 \times 50.0 \times 1.10 \times 0.30 = 16.50 \text{ m}^3$$

$$1 \times 48.0 \times 0.90 \times 0.30 = 12.96 \text{ m}^3$$

$$1 \times 30.0 \times 0.80 \times 0.30 = 7.2 \text{ m}^3$$

$$1 \times 55.0 \times 0.85 \times 0.30 = 14.02 \text{ m}^3$$

$$= 95.97 \text{ m}^3$$

$$\text{Limit} = 91.26 \text{ m}^3$$

② making up of berms -

$$2 \times 50.0 \times 0.95 = 95.0 \text{ m}^2$$

$$2 \times 45.0 \times 0.90 = 81 \text{ m}^2$$

$$2 \times 70.0 \times 0.75 = 105 \text{ m}^2$$

$$2 \times 67.00 \times 0.85 = 113.90 \text{ m}^2$$

$$2 \times 53.00 \times 0.70 = 74.20 \text{ m}^2$$

$$2 \times 50.0 \times 0.60 = 60 \text{ m}^2$$

$$442.9 \text{ m}^2$$

③ Repair of pot holes

1.05th 75mm worm

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Add. gst + 12%					20,275.5
					21,163.00
Add. 1% L. (over)					(+1) 168.54
					21,331.54
					7,99,287.61
					1,90,458.00
					1,90,458.00

Amended
21.06.25
J.E

21/06/25
AE

CKP
check
21/6/25

Material Statement

Soil - 91.26 m³

Stone chips - 7.59 m³

Emulsion - 0.08 mt

Bitumen - 0.56 mt

Amended
21.06.25
J.E