

Schedule XLV-Form No. 134

MBIV - 1314 - 1315

MADE PUD

DIVISION

Chailool

SUB-DIVISION

MMKSY-SC

Measurement Book

Cont Santeev Kumar Singh

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
	Abstract of cost				
Item no ①	Restoration of rain culvert - etc				
	quantity vide TMR				
	P- 39	-	70.	16 M ³ @	
	RS	3.65	25	M ³	
				RS 25625.00	
Item no ②	making up of berm/shoulders - etc				
	quantity vide TMR				
	P- ④0	-	475.	59 M ² @	
	RS	54.6	1	M ²	
				RS 25779.00	
Item no ③	Repair of pot hole				
	quantity vide TMR				
	P- ④0	-	63.	00 M ³	
	@ RS	302.	54	M ³	
				RS 19078.00	
Item no ④	patch repair over bitumen - etc				
	quantity vide TMR				
	P- 40	-	63.	00 M ²	
	@ RS	204.	53	M ²	
				RS 13000.00	
Item no ⑤	repair of G.P. under				
	quantity vide TMR P- ④0				
	- 2	-	00	M ² @ RS	1131.64
	MS			RS	2265.00
Item no ⑥	white washing of parapet				

Continuation

Continuation

42

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
					quantity note THIS P-
	(40)	-			26.52 m ² @
	Ry	16			981 m ²
				Ry	437.00
				Ry	86377.00
Less	10%	-)	Ry		8638.00
					77739.00
			Ry -		85509.00
			Ry		77739.00
Sd/- 03/03/25 T.E.					