

Dy. Shankar Dube

109/2017-18

M.M.C.Sy (Maintenance)

T/MQ21 TOLg TD TUrHg TOLg

Schedule XLV-Form No. 134

Ayeyaj

DIVISION

Ayeyaj

SUB-DIVISION

Measurement Book

37642 3511K. 47610371270.

16

Sch. XLV-Form No. 134

Sch. XLV-Form No. 134

Scanned by CamScanner

ABSTRACT OF COST

18

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Date -	13-05-2022				
① Resurfacing of road					
8 ft wide T.M.B. & Page 16					
Qty = 193.60 m ²					
@ Rs 316.34/m ²					Rs 61243.00
② Making up loss of material					
irregularities on shoulder					
8 ft wide T.M.B. & Page 17					
Qty = 806.96 m ²					
@ Rs 48.92/m ²					Rs 39476.00
③ Repair of pot holes by removal					
8 ft wide T.M.B. & Page 17					
Qty = 78.18 m ²					
@ Rs 310.37/m ²					Rs 24265.00
④ Patch repairs on road already filled					
8 ft wide T.M.B. & Page 17					
Qty = 78.18 m ²					
@ Rs 295.65/m ²					Rs 23114.00
					Rs 148098.00

Continuation

14.05.22 13-05-2022
A.E. J.G.