

SC

Schedule XLV-Form No. 134

SH 76 Toivenigay-Jadiya Se Jawahas
Sak ghar hok huye Hobu **DIVISION** ~~holitok~~

SUB-DIVISION

Bzibhas Kumar Jha.

Measurement Book

MB. No - 629
Bibash Kumar Jha

Sch. XLV—Form No. 134					Contents of area
Particulars	Details of actual measurement				
	No.	L.	B.	D.	
3rd year maintenance Bill					
Abstract of cost					
Name of road: — Construction					
of road from SH 76					
Tiruvengalur to Jawahar					
Sah hotel hue Thakur					
Tola Tax					
Ass no — 136/SBD/MMGSY/ 18-19					
Agency: — Bibhash kr. Jha					
Actual date of completion					
— 20.08.2020					

Item ①	Restoration of raincubs				
15-1					
16.20 m ¹ =	3	30	0.60	0.30	
9.0 m ³ =	2	30	0.50	0.30	
3.0 m ³ =	1	20	0.50	0.30	
28.20 m ³ @ Rs 398.45/m ³					
			= Rs 112	36.00	

Item ②	Maintenance of				
15.2	earthen shoulder -				
63 m ² =	3	30	0.70		
36 m ² =	2	30	0.60		
48 m ² =	2	30	0.80		
10 =	1	20	0.50		
157 m ²	@ Rs	54.16 / m ²			

Continuation = Rs 8503.02

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Item ③ Repair of Pot holes					
15-3(1) felled with 75 mm					
BM - do					
$0.54 \text{ m}^2 =$	4	3.0	0.60	0.075	
$1.35 \text{ m}^2 =$	6	2.50	1.2	0.075	
$0.217 \text{ m}^2 =$	1	2.90	1.0	0.075	
$21107 \text{ m}^2 @ \text{Rs } 10210.17 \text{ m}^2$					
					=Rs 21513.00
Item ④ Patch repair over					
15-3(11) pot holes - do					
$7.20 \text{ m}^2 =$	4	3.0	0.60	0.075	
$18.0 \text{ m}^2 =$	6	2.50	1.20		
$2.90 \text{ m}^2 =$	1	2.90	1.0		
$28.10 \text{ m}^2 @ 217.67 \text{ m}^2$					
					=Rs 6117.00
Item ⑤ Maintenance of					
15-7(1) hpc - do					
1 No @ Rs 1131.64 each					
					=Rs 1132.00
Item ⑥ cutting of branches					
15-12(1) of trees					
1 No @ 118.23 each					
					=Rs 118.00
Item ⑦ cutting of shrubs					
15-12(11) from road way					
4 No @ Rs 6.60 each					
					=Rs 26.00
Total Rs					48645.00

Continuation

—c/o

Material statement		
①	Soil	28.20 m ³
②	Bitumen	0.215 m ³
③	stone chips	3.75 m ³
④	Emulsion	0.02 m ³

Continuation