

कार्यपालक अभियन्ता का कार्यालय
ग्रामीण कार्य विभाग, कार्य प्रमण्डल, बक्सर

पत्रांक 446 /

बक्सर, दिनांक 21.03.2025

प्रेषक:-

कार्यपालक अभियन्ता,
ग्रामीण कार्य विभाग,
कार्य प्रमण्डल, बक्सर।

सेवा में,

नोडल पदाधिकारी,
3054 (M.R) कोषांग,
बिहार, पटना।

विषय:- शीर्ष 3054 नई अनुरक्षण नीति-2018 अंतर्गत Initial Rectification and Surface renewal. कराये गये कार्य हेतु अधियाचना के संबंध में।

महाशय,

उपर्युक्त विषयक कहना है कि विहित प्रपत्र में संलग्न विवरणी के अनुसार शीर्ष Mr 3054 New Maintenance Policy-2018. अन्तर्गत Initial Rectification and Surface renewal. कराये गये कार्य हेतु राशि की आवश्यकता है।

अतः कार्यहित में अनुरोध है कि उक्त अधियाचित राशि उपलब्ध कराने की कृपा की जाय ताकि कराये जा रहे कार्यों का विपत्र भुगतान किया जा सके।

अनु०:- (1) अधियाचना प्रपत्र
(2) IRI Value Report
(3) Map
(4) प्रमाण-पत्र।

विश्वासभाजन


21.3.25

कार्यपालक अभियन्ता
ग्रा०का०वि०, कार्य प्रमण्डल,
बक्सर


21.3.25

FORM GFR 19-A

(See Government of India's Decision (I) below Rule- 150)
Form of Utilization Certificate upto date of 20.03.2025

Name of Scheme :- MR NEW MAINTENANCE POLICY-2018.

Sl. No.	Name of Scheme	Sanction No. & Date with Amount (Rs.In lacs)	Amount Received (Rs.In Lacs)	Particulars
Through C.F.M.S. Received			-	
1	MR NEW MAINTENANCE POLICY-2018.	BF up to 2024-2025 Lt No-02 dt-14.01.2025 <u>12524.36810</u>	12524.36810	Certified that Alltoment Received during the year 2024-2025 Throught C.F.M.S. Rs.12524.36810 lacs of grants-in- favour of Executive Engineer, R.W.D.(W) Division, Buxar. Bihar a sum of Rs.12501.25022 lacs has been utilized for the purpose of MR NEW MAINTENANCE POLICY-2018. schemes as given in the margin for which it was sanctioned and that the balance of Rs.23.11788 lacs remaining unutilized at the end of the period under report.
		Total Rs. =	12524.36810	

- 2 Certified that I have satisfied myself that the conditions on which the grants- in - aid was sanctioned have been duly fulfilled. are being fulfilled and that I have exercised the following checks to see that the money was actually utilized for the purpose for which it was sanctioned.

Kind of Checks exercise:-

- Works have been supervised by Executive Engineer/ Superintending Engineer
- Periodical inspection has been conducted by Executive Engineer/ Superintending Engineer
- Construction materials have been tested.
- Measurements have been recorded in the MBs and test check conducted by the Assistant Engineer/ Executive Engineer.
- All other codal formalities have been observed.

3 **Physical progress achieved:-**

- Construction of Road works.
- Construction of CD works.

D.A.O
R.W.D. (W) Division.
Buxar


21.3.25
Executive Engineer
R.W.D. (W) Division.
Buxar


21.3.25

Name of Division:- RWD Works Division Buxar.

Rural Works Department
MR NEW MAINTENANCE POLICY-2018, ALLOTMENT REQUISITION

Date-20.03.2025

Sl. No.	Year	Name of Road	Name of Contractor (In English)	Project Id	Administrative Sanction		Agreement Amount (In Lacs)		Value of IRB (in mm/km)	Thickness of Bitumen Layer (in mm)	Value of Bitumen Content in Percentage	Allotment Received (in Lacs)	Total Expenditure as per MIS (in Lacs)	Value of Measurement (in Lacs)	Current Demand (in Lacs)	Remarks
39	2023-24	LO21-BUXAR DINARA KAPURPATI TO HARPUR (L21)	Narendra Kumar	10401902074	2.100	104.20700	49.53280	11.46865	2067	25	5%	0.00000	0.00000	49.53280	49.53280	Physically complete

D.A.O
RWD Works Division
Buxar

Executive Engineer
RWD Works Division
Buxar

21.3.25
NE


21.3.25
CM

कार्यपालक अभियंता का कार्यालय
ग्रामीण कार्य विभाग, कार्य प्रमंडल, बक्सर

का0आ0स..... बक्सर/ दिनांक.....


कार्यालय आदेश

प्रमाणित किया जाता है कि बिहार ग्रामीण पथ अनुरक्षण नीती-2018 योजनान्तर्गत L021-BUXAR DINARA KAPURPATTI TO HARPUR (L21) पथ का कार्य गुणवत्ता एवं विशिष्टियों के अनुरूप पूर्ण कराया गया है। पथ के मापीपुस्त की जाँच मेरे द्वारा 10 प्रतिशत, सहायक अभियंता द्वारा 50 प्रतिशत एवं कनीय अभियंता के द्वारा शत प्रतिशत किया गया है।


21.3.25

कनीय अभियंता
ग्रामीण कार्य विभाग
कार्य अवर प्रशाखा ईटाढ़ी

सहायक अभियंता
ग्रामीण कार्य विभाग
कार्य अवर प्रमंडल ईटाढ़ी


21.3.25

कार्यपालक अभियंता
ग्रामीण कार्य विभाग
कार्य प्रमंडल, बक्सर

Name of Road:-L021-BUXAR DINARA KAPURPATTI TO HARPUR (L21) Contractor Name:-Narendra Kumar

Date	Time	Section	No.	Length	Bumps	Speed	OR	IRI	ATEGORY	Latitude	Longitude	Event
20/3/25	08:03:15	58	0.1	200	10.1	2000	1880	G	ROAD	25.51152	84.050251	Normal
20/3/25	08:04:41	58	0.1	210	20.2	2100	1962	G		25.51262	84.050925	Normal
20/3/25	08:05:13	58	0.1	210	20.2	2100	1962	G		25.51284	84.051358	Normal
20/3/25	08:06:07	58	0.1	260	20.2	2600	2370	G		25.51285	84.052442	Normal
20/3/25	08:08:01	58	0.1	210	10.1	2100	1962	G		25.51284	84.051358	Normal
20/3/25	08:09:03	58	0.1	230	10.1	2300	2125	G		25.51285	84.052947	Normal
20/3/25	08:10:25	58	0.1	110	10.1	2200	2044	G		25.5127	84.054106	Normal
20/3/25	08:11:01	58	0.1	210	10.1	2100	1962	G		25.51241	84.05414	Normal
20/3/25	08:12:51	58	0.1	210	10.1	2100	1962	G		25.51205	84.054136	Normal
20/3/25	08:13:05	58	0.1	240	10.1	2400	2207	G		25.51132	84.054185	Normal
20/3/25	08:14:08	58	0.1	230	10.1	2300	2125	G		25.51056	84.054158	Normal
20/3/25	08:16:09	58	0.1	250	10.1	2500	2288	G		25.50953	84.053937	Normal
20/3/25	08:16:56	58	0.1	200	10.1	2000	1880	G		25.50891	84.053846	Normal
20/3/25	08:18:36	58	0.1	230	10.1	2300	2125	G		25.50817	84.053664	Normal
20/3/25	08:19:09	58	0.1	110	10.1	2200	2044	G		25.50988	84.05401	Normal
20/3/25	08:20:01	58	0.1	210	10.1	2100	1962	G		25.50781	84.0536	Normal
20/3/25	08:21:46	58	0.1	210	10.1	2100	1962	G		25.5071	84.053422	Normal
20/3/25	08:22:17	58	0.1	240	10.1	2400	2207	G		25.50647	84.05331	Normal
20/3/25	08:23:05	58	0.1	230	10.1	2300	2125	G		25.50579	84.053148	Normal
20/3/25	08:24:15	58	0.1	250	10.1	2500	2288	G		25.50465	84.052626	Normal
20/3/25	08:25:06	58	0.1	210	20.2	2100	1962	G		25.50188	84.051787	Normal
		Length	2.100									

$$Y = 0 * X^2 + 0.816 * X + 249$$

$$X = 2125$$

$$Y = 2044$$

(R) RURAL ROAD
Good Average Poor
<4000 4001-5000 >5001


IRI value=2067
Machine ID=19195

Yashwanth
31.03.2025
Asst IT Manager

21.3.26
21.3.26

21.3.25
EE

File : C:\Users\VSURYANAND MISHRA\Desktop\06031352.xlsx Section No. : 58, Eqn : test
 Name of Customer : Narendra kumar, Name of Work/ Road : L021- BUXAR DINARA KAPURPATTI TO HARPUR, Lab



Komal Kumar
 01.03.2025
 025.17.17.17

[Signature]
 21.3.26
 21.3.26

[Signature]
 21.3.25
 EE