

2197191714-496186 41019541cm 2490
Schedule XLV-Form No. 134
419 29 4159191111 11169541

DIVISION

SUB-DIVISION

41969 ÷ 21966 42114 2111

MEASUREMENT BOOK

4295-42121 MB 110 ÷ 1289

First Year Maintenance Bill
Sch. XLV-Form No. 131

[illegible]

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
	2	5	15	0.25	121.50m ²
	2	10	20	0.15	300m ²
	2	8	15	0.25	228m ²
	2	7	16	0.25	190.4m ²
	2	8	15	0.25	197.6m ²
	2	7	14	0.25	186.2m ²
	2	7	14	0.25	186.2m ²
	2	7	14	0.25	186.2m ²
	Total Qty:				1400.1m ²

③ Patch Repair on already filled
Pot holes with 75mm do to
all Complete Job.

3	5	0.75	=	11.25m ²	:
5	9	0.75	=	33.75m ²	:
2	2	0.75	=	3m ²	:
3	10	0.75	=	22.5m ²	:
2	4	0.75	=	6m ²	:
2	10.5	0.75	=	15.75m ²	:
Total Qty				92.25m ²	:

④ Maintenance of C/D work

Qty. 8/10

1m²

8/2/25

A.E

Particulars	Q.No.	Area	Rate	Amount
1. Dig down and level				
2. Red soil and 10mm coarse sand and compacted 10cm				
QVTMB P-88	260.55m ²			
@ Rs 402.52			Rs 104716.00	
3. Moulding and repair of 10mm/10mm/10mm & stripping 10cm to all complete job.				
QVTMB P-89	1400.10m ²			
@ Rs 59.90			Rs 83866.00	
4. Patch Repair on already filled				
Pat holes with 75mm clay to all complete job				
QVTMB P-89	92.25m ²			
@ Rs 238.56			Rs 21995.00	
5. Maintenance of CID road clay				
to all complete job.				
QVTMB P-89	9/No			
@ Rs 1166.58			Rs 9333.00	
Total Rs.				199910.00
Add 12% G.S.T			Rs.	23989.00
Add 1% L.C			Rs.	1999.00
Add S.F.			Rs.	34489.00
			Rs	260387.00
Less 0.05% Tied up			Rs	26.00
Chd			Rs	260361.00
8/1/25				
8/1/25				