

Andhr Maintenance Bill

48

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
n/w :- LRP Road To Harijan colony					
Agency :- m/s ability construction					
Agg No :- 39/MMCWS/SGO/19-20					
Actual completion - 05-04-21					

Record Measurement

1) Restoration of Rainwater					
10	30.00	0.90	0.30		81.00 m ³
2	20.00	0.90	0.30		10.80 "
1	10.00	1.25	0.30		3.75 "
1	12.00	1.25	0.30		4.50 "
					100.05 m ³
2) Maints of earthen shoulder					
5	30.00	1.00	-		150.00 m ²
2	28.00	1.00	-		56.00 "
3	30.00	1.00	-		150.00 "
1	20.00	1.00	-		20.00 "
1	16.00	1.00	-		16.00 "
4	20.00	1.00	-		80.00 "
					472.00 m ²
3) Maints of Bituminous Mix Seal					
Surface Road c- Job					
1x 8.10 x 13.0	2				10.53 m ²
1x 15.00 x 1.20	2				18.00 "
1x 12.00 x 1.60	2				19.20 "
Continuation					
1x 9.50 x 0.80	2				7.60 "
1x 6.00 x 0.80	2				4.80 "
1x 5.00 x 1.00	2				5.00 "
					10.12 m ²

Abstract of cost

50

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
1) Restoration of Raincuts					
wide T.M.B Page (48) item (1)					
100.05 m ² @ 386.14 /-					Rs 38633.2
2) Maint of earthen shoulder					
wide T.M.B Page (48) item (2)					
472.00 m ² @ 57.36 /-					Rs 27074.2
3) Maint of Bituminous Mix					
Scal Surface Road c-206					
wide T.M.B Page (48) item (3)					
65.13 m ² @ 303.10 /-					Rs 19786.2
4) Maint of culvert (3/46)					
wide T.M.B Page (49) item (4)					
1.00 No @ 2329.20 /-					Rs 2329.00
5) Maint of Road Sign					
wide T.M.B Page (49) item (5)					
0.20 No @ 1077.82 /-					Rs 216.00
6) Maint of 20m x 46m stone					
wide T.M.B Page (49) item (6)					
0.25 No @ 621.63 /-					Rs 155.00
7) Cutting of branches of Trees.					
wide T.M.B Page (49) item (7)					
3.00 No @ 109.24 /-					Rs 329.00

Scanned with CamScanner