

Bolan to Plasbati

Schedule XLV-Form No. 134

Executive Engineer
R.W.D., Works Division
Basti Purana

MMGSY-(SC)

DIVISION

Basti

SUB-DIVISION

Measurement Book

621 II

Gulshan Ahmad

07.SBD/2018-19/09/5/2018

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
5th Year Abstract of Cost Madhanga					
(1) Restoration of Ruinulas					
(Item 1P - 41)					
83.82 M ² @ RS = 348.17/M ²					= 29209.00
(2) Making up of Berms shoulder					
(Item 2P - 41)					
463.60 M ² @ RS = 51.58/M ²					= 23912.00
(3) Repair of pot holes filled 75MM WPM					
(Item 3P - 42)					
107.60 M ² @ RS = 380.70/M ²					= 40963.00
(4) Patch repair over pot holes 20MM H.B.S.					
(Item 4P - 42)					
107.60 M ² @ RS = 203.76/M ²					= 21925.00
(5) Maint. of Road Sides					
(Item 5P - 42)					
0.19 KM @ RS = 1054.98/KM					= 196.00
(6) Maint. of 200M & KM Stone					
(Item 6P - 42)					
0.30 KM @ RS = 572.66/KM					= 170.00
(7) Cutting of branches of trees & Shurbs					
(Item 7P - 42)					
2.10 NOS @ RS = 102.49/each					= 205.00
(8) Cutting of Shurbs from Roadway.					
(Item 8P - 42)					
10.00 NOS @ RS = 6.29/each					= 63.00
(9) Trimming of grass & weeds.					
(Item 9P - 42)					
8.40 M ² @ RS = 2.10/M ²					= 17.00
					RS = 11666.00

Continuation

[illegible]