

कार्यपालक अभियंता का कार्यालय
ग्रामीण कार्य विभाग, कार्य प्रमंडल, चकिया, (पूर्वी चम्पारण)।

पत्रांक: 815.....अनु0 / चकिया, दिनांक: 13 / 05 / 2025

प्रेषक

कार्यपालक अभियंता,
ग्रामीण कार्य विभाग,
कार्य प्रमंडल, चकिया।

सेवा में,

अपर मुख्य कार्यपालक पदाधिकारी-सह-सचिव,
बिहार ग्रामीण पथ विकास एजेंसी,
ग्रामीण कार्य विभाग, बिहार, पटना।

विषय- विभाग के नई निति रख-रखाव 2018 M.R (3054) योजना के अन्तर्गत निर्माणाधीन कार्य के लिए निधि उपलब्ध कराने के संबंध में।

महाशय,

उपर्युक्त विषय के संबंध में विभाग के नई निति रख-रखाव 2018 M.R (3054) योजना के अन्तर्गत निर्माणाधीन कार्य के लिए पथवार मांगी जाने वाली आवंटन की सूची पत्र के साथ भवदीय के अवलोकनार्थ एवं आवश्यक कार्रवाई हेतु समर्पित की जा रही है।

अतः संलग्न सूची के अनुसार आवंटन उपलब्ध कराने की कृपा की जाय।

अनु0:- 1. आवंटन की सूची।
2. मापी पुस्त की छाया प्रति।
3. Bump Test Integrator Machine

विश्वासभाजन,

कार्यपालक अभियंता,
ग्रामीण कार्य विभाग,
कार्य प्रमंडल-चकिया।

ज्ञापांक- 815 दिनांक- 13-05-2025

प्रतिलिपि-नोडल पदाधिकारी (3054), ग्रामीण कार्य विभाग, बिहार, पटना को सूचनार्थ एवं आवश्यक कार्रवाई हेतु समर्पित।

अनु0:- 1. आवंटन की सूची।
2. मापी पुस्त की छाया प्रति।
3. Bump Test Integrator Machine

कार्यपालक अभियंता,
ग्रामीण कार्य विभाग,
कार्य प्रमंडल-चकिया।

**OFFICE OF THE EXECUTIVE ENGINEER,
RURAL WORKS DEPARTMENT, WORKS DIVISION, Chakia.**

Requisition Format for Scheme Head- MR(3054) under Bihar Rural Road Maintenance Policy-2018 (Initial Rectification and Surface Renewal)

Name of Works Division : Chakia

SI No.	Package No.	Name of Road	Project ID as per MIS	Administrative Approval ((AA) Latter No. & Date	Administrative Approval (AA)			Agreement Amount (In Lakh)		Agreement No. & Date	Date of Completion as per Agreement	Actual Date of Completion	Value of IRI (in mm/km)	Thickness of Bitumen layer (in mm)	Value of Bitumen Content in Percentage	Previous Total Alloted Amount (In lakh)	up-to- date expenditure as per MIS (In Lakh)	Requisition against work done. (In Lakh)	Remarks
					Length (In Km)	Amount of (In Lakh)	Initial Rectification with Surface Renewal (In lakh)	5 Years Routine Maintenance (In Lakh)											
1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	
1	RM/EA/CHA/24/0006	N.H. 28 - Dhubaulia	31708202132	Date- 01.03.2024 Latter No.1086	3.120	170.97000	130.24452	26.06809	Date- 29.10.2024 10 MBD/2024-25	28.07.2025	Work in Progress	3002.00	25	5.00	72.37747	72.37747	57.76348	Work in Progress	
2	RM/EA/CHA/24/0006	PMGSY Road Harnaina to Naya Tola Harnaina via Prathmik vidyalaya Harnaina	31708412008	Date- 01.03.2024 Latter No.1086	1.250	73.99000	57.30142	10.25167	Date- 29.10.2024 10 MBD/2024-25	28.07.2025	Work in Progress	3007.00	25	5.00	30.19339	30.19339	27.05885	Work in Progress	
					4.370	244.960	187.54594	36.31976							102.571	102.571	84.82233		

1 Signed Hard Copy and Soft Copy (in excel) of recorded IRI is enclosed.

1 Signed Hard Copy and Soft Copy (in excel) of recorded IRI is enclosed.

2 Up-to-date Physical Progress has been uploaded in MIS.


 Executive Engineer,
 Rural Works Department,
 Works Division, Chakia.
 13/05/25

Form GER 19-A
 (See Government of India's decision (1) below Rule - 150)
Form of utilization certificate up to the month up to 05/2025
M.R. (3054) New maintenance Policy-2018.

PIU - RWD , W.D- CHAKIA

SL. NO	Name of Scheme	Sanction No. / Date with Amount (in RS. Lachs)	Amount Received (in RS. Lacks)	particulars
1	M.R. (3054) New maintenance Policy-2018	13191.35483	13191.35483	Certified that out of Rs.13191.35483 Lakh Receive upto the Month, May-25 (F.Y 2025-26) executive engineer RWD, (W) DIV, chakia a sum of RS.12590.17613 Lakh has been utilized for the perpose of M.R. (3054) New maintenance Policy-2018 'CFMS' Schemes given in the margin for which it was sanctioned and that the balance of Rs.601.17870 lakh remaining unutilized at this end of the (up to 05/2025)

2. Certificate that I have satisfied myself that the conditions on which the grand's-in-aid was sanctioned have been duly fulfilled/ate being fulfilled and that have exercised the following checks to see that the money was actually utilized for the purpose for which it was sanctioned kinds of cheks exercised:-

- Works have been supervised by Executive Engineer/ Superintending Engineer.
- Periodical inspection has been conducted by Executive Engineer/ Superintending Engineer.
- Construction materials have been tested.
- Measurements have been recorded in the MBs and test check conducted by the Assistant.

3. Physical Progress achieved :-

- Construction of M.R. (3054) New maintenance Policy-2018 (Details in Progress report)
- Construction of Road Works. (.....Do.....)

Executive Engineer,
Rural Works Department,
Works Division, Chakia.

13/05/25

Name of work : PMGSY Road Harnaraina to Naya Tola Harnaraina Via Prathmik vidyalaya Harnaraina

Name of customer : Dharendra Construction Private Limited

(R)Rural Road

							Good		Average					Poor							
							< 4000					4001 - 5000					> 5000				
												Test No	Time	Distance(m)	Total Distance(m)	BUMP(cm)	Speed(Km/Hr)	UI(mm/Km)	Corrected UI (mm/Km)	IRI	Status
08/03/25	17:40:46	71	100	100	100	32.0 cm	25.6 Km/Hr	3200.0 mm/Km	3171	4.23	Good	26.4671415	N	84.9826064	E	Normal					
08/03/25	17:41:01	71	100	200	200	31.0 cm	23.4 Km/Hr	3100.0 mm/Km	3079	4.12	Good	26.4666871	N	84.9820742	E	Normal					
08/03/25	17:41:14	71	100	300	300	30.0 cm	27.0 Km/Hr	3000.0 mm/Km	2986	4.01	Good	26.4662742	N	84.9817991	E	Normal					
08/03/25	17:41:26	71	100	400	400	33.0 cm	31.5 Km/Hr	3300.0 mm/Km	3264	4.34	Good	26.4661784	N	84.9818095	E	Normal					
08/03/25	17:41:36	71	100	500	500	32.0 cm	33.4 Km/Hr	3200.0 mm/Km	3171	4.23	Good	26.4661655	N	84.9818299	E	Normal					
08/03/25	17:41:47	71	100	600	600	33.0 cm	33.4 Km/Hr	3300.0 mm/Km	3264	4.34	Good	26.4651293	N	84.9814137	E	Normal					
08/03/25	17:41:57	71	100	700	700	32.0 cm	36.0 Km/Hr	3200.0 mm/Km	3171	4.23	Good	26.4651313	N	84.9814154	E	Normal					
08/03/25	17:42:11	71	100	800	800	30.0 cm	26.7 Km/Hr	3000.0 mm/Km	2986	4.01	Good	26.4651323	N	84.9814182	E	Normal					
08/03/25	17:42:24	71	100	900	900	36.0 cm	27.7 Km/Hr	3600.0 mm/Km	3542	4.67	Good	26.4635726	N	84.9808773	E	Normal					
08/03/25	17:42:37	71	100	1000	1000	30.0 cm	27.3 Km/Hr	3000.0 mm/Km	2986	4.01	Good	26.4619552	N	84.9812911	E	Normal					
08/03/25	17:42:49	71	100	1100	1100	24.0 cm	29.7 Km/Hr	2400.0 mm/Km	2430	3.34	Good	26.4588026	N	84.9835083	E	Normal					
08/03/25	17:43:04	71	100	1200	1200	24.0 cm	25.2 Km/Hr	2400.0 mm/Km	2430	3.34	Good	26.4576471	N	84.9841861	E	Normal					
08/03/25	17:43:18	71	100	1300	1300	26.0 cm	24.6 Km/Hr	2600.0 mm/Km	2615	3.56	Good	26.4572241	N	84.9844193	E	Normal					


AVG IRI-3007

10-3-25
J.F.

10/03/25
J.F.

कायपासिक अधिकारी
ग्रामीण कार्य विभाग
कार्ग प्रमंडल चक्रिया

Dhirendra Construction Private Limited , Machine no: 19191 , Road: PMGSY Road Harnaraina to Naya Tola Harnaraina Via Prathmik vidyalaya Harnaraina , Date: 08-03-25 , Section No: 71 , Equation:





CSPO
10-3-25
J.E

17/03/25
Me


Sunil Kumar
कार्यपालक प्रमुख
ग्रामीण कार्य विभाग
कार्य प्रबंधन

2nd 201/2 Bill

Sch. XLV-Form No.134 17

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Name of work - construction of road from pmgsy road Harnarain to Haya to Harnarain via prathmik viaduct					
Harnarain					
Package no - MP-1/23-24 Chakia/09					
Agency - Dhikshila town					
Agreement No - 10MB 12024-25					
Date of work order - 29-10-24					
Date of completion - 28-7-25					
further measurement taken after					
 16/04/25 PE  16/04/25 PE					

16/11/25

ABSTRACT of cost

112/20

providing typical

sign board

vide TMB P-11

Qty 3 nos

@ 17160.52/A=RS 51482.00 ✓

(3/1)

clearing & grubbing

road land

vide TMB P-11

Qty 0.25 Hec

@ RS 76926.08/Hec RS 19232.00 ✓

(1/1)

Gravel 8+11

vide TMB P-11

Qty 27.12 m³


@ 349000/1000 RS 94735.00 ✓

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
$\frac{5}{5}$	WBH 172				
	vide TMB-P. 4				
8	Qty - 59.58 m ³				
	① 2. 5392:13			2. 321263:0	
$\frac{6}{6}$	WBH 172				
	vide TMB-P. 5				
	Qty - 104.70 m ³				
	① 2. 4985:20			2. 521950:0	
4/10	Consto. of D.L.C.				
	vide TMB-P. 5				
	Qty - 11.20 m ³				
	① 2. 7924:70			2. 88757:0	
$\frac{8}{11}$	PCC 130 grade.				
	vide TMB-P. 6				
	Qty - 189.38 m ³				
	① 2. 9610:17			2. 1819974:0	
$\frac{9}{7}$	P.V. & app. Prime coat				
	vide TMB-P. 6				
	Qty - 1396.00 m ²				
	① 2. 54:42			2. 75970:0	
$\frac{10}{8}$	P.V. & app. Pack coat				
	vide TMB-P. 7				
	Qty - 3219.38 m ²				
	① 2. 18:68			2. 60138:0	
$\frac{11}{9}$	P.V. & app. S.D.B.C.				
	100-120 TMB				

Continuation

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
		vide THB-P 7			
		Qty - 80.48 m ³			
		① R. 13916.02			Q. 1119961.0
$\frac{120}{3}$		Subgrade & earthwork shoulder			
		1000y 1-1			
		vide THB-P 12			
		Qty - 450.00 m ³			
		① R. 264.51			Q. 117029.0
$\frac{110}{2}$		Subgrade & earthwork shoulder			
		100y 1-1			
		vide THB-P 12			
		Qty - 656.40 m ³			
		① R. 188.27			Q. 123580.0
$\frac{130}{19}$		Road Marking for			
		RCC			
		vide THB-P 13			
		Qty - 80.00 m ²			
		① R. 1005.95			Q. 80476.0
$\frac{10}{18}$		Road Marking for			
		B.T			
		vide THB-P 13			
		Qty - 170.40 m ²			
		① R. 886.50			Q. 150705.0
$\frac{14}{12}$		K.M Stone.			
		THB-P-13, Qty - 3 Nos			
		① R. 3273.53			Q. 9821.0

Continuation

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
$\frac{15}{13}$	2nd 4 store				
	vide TMB-P-13				
	Qty - 5 Nos				
	② 868:67			2.	4343-0
$\frac{16}{14}$	600mm 				
	vide TMB-P-13				
	Qty - 4 Nos				
	② 6568:56			2.	18274-0
$\frac{17}{15}$	600mm 				
	vide TMB-P-13				
	Qty - 4 Nos				
	② 6018:18			2.	24073-0
$\frac{18}{16}$	600mm x 450mm 				
	vide TMB-P-14				
	Qty - 2 Nos				
	② 5044:81			2.	10090-0
$\frac{17}{21}$	Plastering work in ch				
	vide TMB-P-14				
	Qty - 5.76 m ³				
	② 8836:87			2.	50900-0
$\frac{18}{22}$	Plastering with ch				
	vide TMB-P-14				
	Qty - 40.32 m ²				
	② 237:89			2.	9592-0
$\frac{19}{23}$	Painting two coat incl				
	diy prime coat				

Continuation

