

कार्यपालक अभियंता का कार्यालय
ग्रामीण कार्य विभाग, कार्य प्रमंडल खड़गपुर-तारापुर (मुंगेर)

पत्रांक:- 825 (अनु०) / तारापुर दिनांक 14 / 05 / 2025
प्रेषक,

कार्यपालक अभियन्ता,
ग्रामीण कार्य विभाग,
कार्य प्रमंडल, खड़गपुर-तारापुर।

सेवा में,

अपर मुख्य कार्यपालक पदाधिकारी-सह-सचिव,
बिहार ग्रामीण पथ विकास अभिकरण (ब्राडा), पटना।

विषय :- New Maintenance Policy-2018 अन्तर्गत 4 पथों में कराये गये निर्माण कार्यों का आवंटन उपलब्ध कराने के संबंध में।

महाशय,


उपर्युक्त विषय के संबंध में कहना है कि New Maintenance Policy-2018 अन्तर्गत 4 पथों में कराये गये निर्माण कार्यों के भुगतान हेतु संलग्न विवरणी के अनुसार **रु०-123.43954 लाख** राशि की आवश्यकता है।

अतः अनुरोध है कि उक्त राशि का आवंटन उपलब्ध कराया जाए, ताकि संवेदक को भुगतान किया जा सके।

सूचनार्थ एवं आवश्यक कार्रवाई हेतु समर्पित।

अनु०- यथोक्त

विश्वासभाजन



कार्यपालक अभियंता


ग्रामीण कार्य विभाग

कार्य प्रमंडल खड़गपुर-तारापुर

**Office Of The Executive Engineer
Rural Works Department
Works Division, Kharagpur-Tarapur**

Requisition Format for Scheme Head - MR(3054) under Bihar Rural Road Maintenance Policy - 2018 (Initial Rectification and Surface Renewal)

Sl. No.	Package No.	Name of Road	Project ID as per MIS	Administrative Approval(AA) Letter No. & Date	Administrative		Agreement Amount		Agreement No. & Date	Date of Completion as per Agreement	Actual Date of Completion	Value of IRI (in mm/Km)	Thickness of Bitumen Layer in mm	Value of Bitumen content in Percentage	Previous Total Allocated Amount (in Lakh)	Up-to-date Expenditure as per MIS (in Lakh)	Requisition against work done (in Lakh)	Remarks
					Length (in Km)	Amount (in Lakh)	Initial Rectification with Surface Renewal (in Lakh)	5 Year Routine Maintenance (in Lakh)										
1	RM/MU/KHA/24/0006	L041-R.W.D ROAD L040 TO SANRHI (VR41)	20803802053	6120 04-12-2023	0.790	30.11100	26.52539	5.7378	11MBD/2024-25 09.08.2024	08.05.2025	-	2792	SDBC-25mm Thickness of PCC Layer in 125 mm	SDBC-5.0	0.00000	0.00000	25.52539	Completed
2	RM/MU/KHA/24/0006	L031-GANAILI TO HARPUR (VR31)	20803802045	6120 04-12-2023	2.800	90.40900	79.51841	23.24595	11MBD/2024-25 09.08.2024	08.05.2025	-	2880	SDBC-25mm Thickness of PCC Layer in 125 mm	SDBC-5.0	0.00000	0.00000	77.51841	Completed
3	RM/MU/KHA/24/0004	R.E.O. ROAD MAKAWA SARHI ROAD - MIZAPUR	20803702047	6120 04-12-2024	0.860	26.70100	23.53307	7.40615	51MBD/2023-24 16.03.2024	15-12-2024	14.11.2024	2744	SDBC-25mm	SDBC-5.0	13.53307	14.02084	0.48777	Completed
4	RM/MU/KHA/24/0006	L022-T04 RAJA RANI TALAB ROAD TO HARIJAN TOLA DHAI POKEAR (TRACK22)	20803802032	-	1.260	48.14200	47.16009	7.63935	11MBD/2024-25 09.08.2024	08-05-2025	-	2785	SDBC-25mm Thickness of PCC Layer in 125 mm	SDBC-5.0	27.25212	27.25212	19.90797	Completed
																TOTAL	123.43954	


Divisional Engineer
Rural Works Department
Works Division Kharagpur-Tarapur


Executive Engineer,
Rural Works Department
Work(s) Division Kharagpur-Tarapur


ENGINEER, WORK DEPARTMENT, WORKS DIVISION ,KHARAGPUR-TARAPUR,(MUNGER)
FORM GFR19 A


(See Government Of India'S Decesion (1) Below Rule 150)
(Form Of Utilization Certificate up To The Month Of Up To May-2025)

New Maintenance Policy-2018

SL. No.	Name Of Scheme/Purpose	Sanctioned Amounts(In Lacs-Rs.)	Amount Recived(IN Rs. Lacs)	Particulars
1	Construction of Rural Road under New Maintenance Policy-2018	14809.06	14809.06	Certified that Out of Rs.14809.06 lakh received up to date In Favour Of Executive Engineer , RWD, Kharagpur-Tarapur Sum of Rs.14740.09 lakh has been utilized for the purpose of New Maintenance Policy-2018 scheme as given in the margin for which it was sanctioned and that the balance Of Rs.150.42 lakh remaining unutilized amount at the end of the period under.

- 2 Certified that I have satisfied myself that the condition on which the grants in aid was sanctioned have been duly
Fulfiled /are being Fulfiled And that I have Exercised the Checks to see that the money was actually utillized for which it was Sanctioned.


14105125
Divisional Accounts Officer-I
R.W.D. (W) Div, Kharagpur-
Tarapur (Munger)


14105125
Executive Engineer
R.W.D. (W) Div, Kharagpur-Tarapur
(Munger)
4/6/25
14/05/25

Name of work : L031-GANAILI TO HARPUR (VR31)

Name of customer : Pravin Kumar Parsuh

(R)Rural Road

Good	Average	Poor
< 4000	4001 - 5000	> 5000

Date	Time	Test No	Distance(m)	Total Distance(m)	BUMP(cm)	Speed(Km/Hr)	UI(mm/Km)	Corrected UI (mm/Km)	IRI	Status	Latitude	Direction	Longitude	Direction1	Remarks
05/05/25	16:15:10	04	100	100	26.0 cm	15.1 Km/Hr	2600.0 mm/Km	2744	3.72	Good	25.064569	N	86.643085	E	Normal
05/05/25	16:15:33	04	100	200	29.0 cm	20.2 Km/Hr	2900.0 mm/Km	3035	4.07	Good	25.064951	N	86.642239	E	Normal
05/05/25	16:15:54	04	100	300	25.0 cm	25.3 Km/Hr	2500.0 mm/Km	2647	3.6	Good	25.065360	N	86.641367	E	Normal
05/05/25	16:16:16	04	100	400	27.0 cm	28.4 Km/Hr	2700.0 mm/Km	2841	3.84	Good	25.065552	N	86.640756	E	Normal
05/05/25	16:16:34	04	100	500	30.0 cm	26.5 Km/Hr	3000.0 mm/Km	3132	4.19	Good	25.065773	N	86.639790	E	Normal
05/05/25	16:16:57	04	100	600	25.0 cm	25.6 Km/Hr	2500.0 mm/Km	2647	3.6	Good	25.065689	N	86.638861	E	Normal
05/05/25	16:17:21	04	100	700	28.0 cm	21.0 Km/Hr	2800.0 mm/Km	2938	3.95	Good	25.066006	N	86.637934	E	Normal
05/05/25	16:17:44	04	100	800	26.0 cm	23.5 Km/Hr	2600.0 mm/Km	2744	3.72	Good	25.066140	N	86.636919	E	Normal
05/05/25	16:18:07	04	100	900	30.0 cm	23.3 Km/Hr	3000.0 mm/Km	3132	4.19	Good	25.066167	N	86.636037	E	Normal
05/05/25	16:18:31	04	100	1000	26.0 cm	21.1 Km/Hr	2600.0 mm/Km	2744	3.72	Good	25.066134	N	86.635255	E	Normal
05/05/25	16:18:52	04	100	1100	29.0 cm	19.3 Km/Hr	2900.0 mm/Km	3035	4.07	Good	25.066032	N	86.634258	E	Normal
05/05/25	16:19:15	04	100	1200	26.0 cm	19.6 Km/Hr	2600.0 mm/Km	2744	3.72	Good	25.066161	N	86.633306	E	Normal
05/05/25	16:19:33	04	100	1300	30.0 cm	21.3 Km/Hr	3000.0 mm/Km	3132	4.19	Good	25.065742	N	86.632361	E	Normal
05/05/25	16:19:57	04	100	1400	25.0 cm	24.3 Km/Hr	2500.0 mm/Km	2647	3.6	Good	25.065358	N	86.631524	E	Normal
05/05/25	16:20:23	04	100	1500	27.0 cm	24.2 Km/Hr	2700.0 mm/Km	2841	3.84	Good	25.065489	N	86.630563	E	Normal
05/05/25	16:20:48	04	100	1600	25.0 cm	18.7 Km/Hr	2500.0 mm/Km	2647	3.6	Good	25.065948	N	86.629657	E	Normal
05/05/25	16:21:11	04	100	1700	26.0 cm	16.3 Km/Hr	2600.0 mm/Km	2744	3.72	Good	25.066588	N	86.628969	E	Normal
05/05/25	16:21:26	04	100	1800	32.0 cm	21.4 Km/Hr	3200.0 mm/Km	3326	4.42	Good	25.067364	N	86.628513	E	Normal
05/05/25	16:21:47	04	100	1900	28.0 cm	22.7 Km/Hr	2800.0 mm/Km	2938	3.95	Good	25.067867	N	86.627697	E	Breaker
05/05/25	16:22:01	04	100	2000	24.0 cm	24.1 Km/Hr	2400.0 mm/Km	2550	3.49	Good	25.068316	N	86.626858	E	Normal
05/05/25	16:22:17	04	100	2100	30.0 cm	23.5 Km/Hr	3000.0 mm/Km	3132	4.19	Good	25.069243	N	86.626113	E	Normal

Name of work : L031-GANAILI TO HARPUR (VR31)

Name of customer : Pravin Kumar Parsuh


(R) Rural Road

(r)/kural Road															
Good				Average				Poor							
< 4000				4001 - 5000				> 5000							
05/05/25	16:22:29	04	100	2200	26.0 cm	26.2 Km/Hr	2600.0 mm/Km	2744	3.72	Good	25.068055	N	86.625317	E	Normal
05/05/25	16:22:53	04	100	2300	31.0 cm	24.6 Km/Hr	3100.0 mm/Km	3229	4.3	Good	25.068090	N	86.624589	E	Normal
05/05/25	16:23:10	04	100	2400	29.0 cm	22.3 Km/Hr	2900.0 mm/Km	3035	4.07	Good	25.067299	N	86.623973	E	Normal
05/05/25	16:23:31	04	100	2500	25.0 cm	25.8 Km/Hr	2500.0 mm/Km	2647	3.6	Good	25.067325	N	86.623141	E	Normal
05/05/25	16:23:54	04	100	2600	28.0 cm	26.1 Km/Hr	2800.0 mm/Km	2938	3.95	Good	25.067536	N	86.622256	E	Normal
05/05/25	16:24:11	04	100	2700	29.0 cm	22.3 Km/Hr	2900.0 mm/Km	3035	4.07	Good	25.067091	N	86.621451	E	Normal
05/05/25	16:24:31	04	100	2800	25.0 cm	25.8 Km/Hr	2500.0 mm/Km	2647	3.6	Good	25.066216	N	86.620824	E	Normal

[Signature]

05/05/25
[Signature]

Name of Customer: Pravin Kumar Parsuh , Machine no: 19213 , Road: L031-GANAILI TO HARPUR (VR31), Date: 02-05-25, Section No: 4 , Equation: $Y=0.969X+224.9$



Pravin Kumar Parsuh
02-05-25