

Jamal Mahatab

સાધારણ શરૂ કરવામાં આવેલું

(MGSY GEN)

21
m.B.
AB
3/1/22

Schedule XLV-Form No 134

જામલ મહતાબ

R. u D (u) SASARIM DIVISION

R. u D (u) KACHAS SUB-DIVISION

Measurement Book

3063



CamScanner

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Name of Work - Jagdishpur More					
to Jagdishpur					
Name of Cont. - Jambal Masjid					
Agg. No - 22/SRD/2019-20					
Date of start - 17/09/2019					
Date of comp. - 18.06.2020					
Entry Bill - ^{Actual date of Comp/2020} - 12/02/2021					
① Restoration of Raincuts to -					
Soil maximum cut do -					
$3 \times 4.85 \times 1.10 \times 0.30 =$					$4.805 m^3$
$4 \times 4.43 \times 1.05 \times 0.30 =$					$5.5818 m^3$
					$10.38 m^3$
② Making up of Road do -					
$5 \times 9.2 \times 1.10 =$					$50.6 m^2$
$6 \times 9.55 \times 1.10 =$					$63.03 m^2$
					$113.63 m^2$
③ Patch Repair Over Bitumen -					
$4 \times 1.25 \times 0.85 =$					$4.25 m^2$
④ Maint. - Road signs do -					
$1 \times 0.04 =$					$0.04 km$
⑤ Maint. 200 m & kerston -					
$1 \times 0.05 =$					$0.05 km$
⑥ Cutting branches trees shrubs -					
$1 \times 1 =$					$1.00 No.$

Continuation

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Name of Work - Maint. of Road from					
Jagdishpur More to Jagdishpur					
Agency - Jamal Mahtab					
Agg. No - 22/SBD/2019-20					
Date of Start - 19/09/2019					
Date of Comp. - 18/06/2020					
Actual date of Comp. - 12/06/2020					
Date of entry - 10/03/2023					
Road length - 0.425m					
① Restoration of Raincuts Broom					
with Soil maximum dia - dia					
$3 \times 4.85 \times 1.10 \times 0.30$					$= 4.805 m^3$
$4 \times 5.50 \times 1.05 \times 0.30$					$= 6.93 m^3$
					$11.735 m^3$
② Making up of Broom/shoulder					
Surface level etc do do					
$3 \times 4.20 \times 1.15$					$= 14.040 m^2$
$4 \times 3.65 \times 1.125$					$= 16.425 m^2$
$6 \times 3.45 \times 1.10$					$= 49.17 m^2$
$5 \times 7.45 \times 1.10$					$= 40.975 m^2$
$4 \times 3.40 \times 1.115$					$= 15.164 m^2$
					$135.783 m^2$
③ Patch repair Over Bitumen					
Surface with 20mm mix Seal					
do do					
$4 \times 1.25 \times 0.85$					$= 4.25 m^2$
$5 \times 1.25 \times 0.85$					$= 5.1 m^2$
					$= 9.61 m^2$
					$9.35 m^2$

Continuation

[illegible]

Materials Statement

1) $E/w \rightarrow 32.102 \text{ m}$

3rd Year Maint. Bill

45

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Name of work - Maint. of Road from					
Jagdishpur	max to Jagdishpur				0.105 km
Agency -	Jamal Mahatab				
App. No -	22/SRD/2019-20				
Date of start -	13/03/2019				
Actual date of Comp. -	17/03/2021				
(1) Restoration of Rainwater drains					
with soil mounds do					
	3	4	1	0	$1.10 \times 0.30 = 4.059 \text{ m}^3$
	4	5	6	0	$1.20 \times 0.30 = 8.064 \text{ m}^3$
	3	2	3	0	$1.15 \times 0.30 = 2.38 \text{ m}^3$
					$= 14.503 \text{ m}^3$
(2) Making up of Berms/shoulders					
stripping do					
	4	4	.30	1	$1.15 = 25.8 \text{ m}^3$
	5	3	.60	1	$1.12 = 20.16 \text{ m}^3$
	6	5	.80	1	$1.20 = 41.76 \text{ m}^3$
	5	6	.80	1	$1.10 = 37.4 \text{ m}^3$
	7	4	.55	1	$1.10 = 35.035 \text{ m}^3$
					$= 159.35 \text{ m}^3$
(3) Repair of pot holes filled					
75 mm $\frac{1}{2}$ BM do					
	2	1	.75	5	$0.5 = 1.75 \text{ m}^3$
	3	1	.3	5	$0.5 = 5.625 \text{ m}^3$
	4	1	.2	5	$0.5 = 5.5 \text{ m}^3$

Continuation

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
I. No (7/11) 1. No @ 114.84 =					115.00
(8) Road marking on B.T. —					
Qty vide TMB P.No — (46)					
I. No (8/13) 41m ² @ 806.23 =					33055.00
(9) Road marking on C.C. surface					
Qty vide TMB P.No — (46)					
I. No (9/14) 40m ² @ 900.06 =					36002.00
Total RS 2					94459.00
Less 10% Below RS 100 =					9446.00
RS =					85013.00
36 20/03/24					
36 20/03/24					