

Memor to Tenteria

MBNO - 1408

Schedule XLV-Form No. 134

Madhobaria

DIVISION

SUB-DIVISION

MEASUREMENT BOOK

Dimi Kiemar

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
2nd Year Maintenance, Work					
ABSTRACT OF COST					
① Restoration of Raincuts with soil from the shoulder etc. comp. as per T&S					
Qty vide TMA Pg No-65, Item No-1					
					40.57 m ³
					@ RA 359.59/m ³ RA 15400.00
② Making up of base by stripping excess soil from the shoulder etc. comp. as per T&S					
Qty vide TMA Pg No-65-66, Item No-2					572.20 m ²
Qty vide TMA Pg No-67, Item No-7					114.98 m ²
					886.67
					= 886.67 m ²
					@ RA 56.81/m ² RA 39009.00
③ Patch Repair over bituminous surface, etc. comp. as per T&S					
Qty vide TMA Pg No-66, Item No-3					15.67 m ²
Qty vide TMA Pg No-67, Item No-8					14.72 m ²
					30.44 m ² RA 54409.00

Continuation

