

कार्यपालक अभियंता का कार्यालय
ग्रामीण कार्य विभाग, कार्य प्रमंडल, सहरसा

Email ID:-ee.saharsa.rwd2@gmail.com

Mob:- 8986915395

पत्रांक.- 2410

सहरसा/दिनांक.- 08-11-25

प्रेषक,

कार्यपालक अभियंता,
ग्रामीण कार्य विभाग,
कार्य प्रमंडल, सहरसा

सेवा में,

नोडल पदाधिकारी (RRSMP)
ग्रामीण कार्य विभाग
पटना, बिहार

विषय :- ग्रामीण सड़क सुदृढीकरण एवं प्रबंधन कार्यक्रम योजना के अंतर्गत पुल में कराये गये कार्य के विरुद्ध हेतु आवंटन उपलब्ध कराने के संबंध में।

महाशय,

उपरोक्त विषय के संबंध में सूचित करना है कि ग्रामीण सड़क सुदृढीकरण एवं प्रबंधन कार्यक्रम योजना के अंतर्गत पुल में कराये गये कार्य के लिए संदेदक को भुगतान करने हेतु अधियाचना विहित प्रपत्र में भरकर आवश्यक कार्यवाही हेतु समर्पित की जा रही हैं।

अतः अनुरोध है कि पथों में कराये गये कार्य हेतु आवंटन उपलब्ध कराने की कृपा की जाए।

अनु :- यथोक्त।

दिश्वसभाजन

कार्यपालक अभियंता,
ग्रामीण कार्य विभाग,
कार्य प्रमंडल, सहरसा।

805
08-11-25

08/11/25

GENERAL FINANCIAL RULES 2017
Ministry of Finance
Department of Expenditure

GFR 12-B
[See Rule 256 (2)]

FORM OF UTILIZATION CERTIFICATE

(1) Certified that out of the Loan of Rs.- 1942.84736, Sanctioned under RRSMP Road., dated....., in favour of Executive Engineer, RWD Works Division, Saharsa during the year 2025-26, an amount of Rs. 1942.84736, has been utilized for the purpose for which it was sanctioned, and that the balance of Rs. 0.00, remaining unutilized at the end of the year..... has been surrendered to the Government (vide No....., dated.....)/ will be adjusted towards the loan payable during the next financial year.

(2) Certified that I have satisfied myself that the conditions on which the loan was sanctioned have been duly fulfilled/are being fulfilled and that I have exercised the following checks to see that the money was actually spent for the purpose for which the loan was made.

Kinds of checks exercised

- 1.
- 2.
- 3.
- 4.

Signature.....

Designation.....

Date.....

815
08.11.25
Divisional Account Officer
RWD Works Division,
Saharsa

Boe
811125
Executive Engineer
RWD Works Division,
Saharsa

Requisition Form for Scheme MMGSUY (RRSNIP)

Name of Works Division : Saharsa

Name of Works Division : Saharsa																		
Package No	Project ID As per MIS	Name of Road	AA Length (In km)	Administrative Approval (Construction Work) Amount in Lac	Agreement (Construction Work) Amount in Lac	Agreement No. & Date	Date of Completion as per Agreement	Actual Date of Completion	Work Status (VBM/VMM, MBBV/SDHC etc)	Value of IRI (In million)	Thickness of Bitumen Layer (In mm)	Value of Bitumen Content (In %)	Total Previous Allocated Amount (In lac)	Upto Date Expenditure as per MIS (In Lac)	Value of Work done (In lac)	Current Demand (In lac)	Remarks	
1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19
RRSNIP/ 24-25	4090430350014	SH 22 ROAD MAHARSHI MEHI SATISANG BHAWAN TO MUSLIM TOLA HOPE HUE PMGSY ROAD	0.700	28.606	28.79951	09/05/2025	08/05/2026	-	SDBC	3572	25mm	5%	0.00000	0.00000	27.50233	27.50233	Kalira	
Saharsa 01																		
Total			0.700	28.606	28.79951								0.00000	0.00000	27.50233	27.50233		


Divisional Account Officer
RWD Works Division,
Saharsa

Executive Engineer
RWD Works Division
Saharsa


अधियाचना हेतु प्रमाण-पत्र

प्रमाणित किया जाता है कि ग्रामीण सड़क सुदृढीकरण एवं प्रबंधन कार्यक्रम योजनान्तर्गत:-

1. पथ एसएच 22 रोड महर्षि मेंहीं सत्संग भवन से मुस्लिम टोले होते हुए पीएमजीएसवाई रोड में कराये गये कार्य की गुणवत्ता जाँच की गयी है जो निर्धारित मानक/विशिष्टियों के अनुरूप हैं।
2. अद्यतन कराये गये कार्य की मापी पुस्तिका में दर्ज है जिसका सत्यापन कर लिया गया है।


02/11/2025

कनीय अभियंता
ग्रामीण कार्य विभाग
कार्य प्रशाखा, क.क.र.


02.11.2025

सहायक अभियंता
ग्रामीण कार्य विभाग
कार्य अवर प्रमंडल, क.क.र.



02/11/25

कार्यपालक अभियंता
ग्रामीण कार्य विभाग
कार्य प्रमंडल, सहरसा

Name of Road:- SH 22 Road Maharshi Mehi Satsang Bhawan to Muslim Tola Hue PMGSY Road Name of Contractor:- M/S Sunrise Construction

Date	Time	Section No.	Length in km	Bumps in mm	Speed Rate	OR mm/km	IRI mm/km	CATEGORY	Latitude	Longitude	Event
01/11/25	10:43:10	99	0.1	300	0	3000	3588 G	ROAD	24.6177	84.845353	Curve
01/11/25	10:43:10	99	0.1	280	10.1	2800	3361 G		24.617442	84.846093	Normal
01/11/25	10:43:10	99	0.1	280	20.2	2800	3361 G		24.617442	84.846093	Normal
01/11/25	10:43:10	99	0.1	320	20.2	3200	3816 G		24.617115	84.846447	Speed Breaker
01/11/25	10:44:19	99	0.1	320	30.3	3200	3816 G		24.616663	84.847087	Normal
01/11/25	10:44:19	99	0.1	300	20.2	3000	3588 G		24.616625	84.847137	Normal
01/11/25	10:46:5	99	0.1	290	10.1	2900	3475 G		24.616372	84.847423	Normal
Average IRI							3572				


$Y = 0 * X^2 + 1.136 * X + 181$
 $X = 2900$
 $Y = 3475$
 (R) RURAL ROAD
 Good Average Poor
 <4000 4001-5000 >5001


 02/11/2025
 J-F


 02.11.2025
 A.C.


 Sunrise

File : E:\Steco Bumb Indicator Report\RRSMP\01111239.xlsx Section No. : 99. Eqn : $Y = 0 * X^2 + 1.136 * X + 181$
 Name of Customer : M/S Sunrise Construction. Name of Work/ Road : SH22 Road Marashi Mehi Satsang Bhawan to



[Signature]
 02/11/2025
 J.E

[Signature]
 02.11.2025
 A.E

[Signature]
 8.11.25