

Sukhasan bukti Road gotk To/a jave Wali Saalat me
Sas ma To/a To Sukhasan Rai yadla To/a.
Schedule XLV-Form No. 134

MB No - 1603

Madhepura DIVISION

Dingraha SUB-DIVISION

MEASUREMENT BOOK

Mukesh kumar

Part - II

ABSTRACT OF COST

1	Restoration of Raincuts
	Qty = 136.117 M^3 (vide T.M.B-P-28)
	@ RS 379.59/M ³ — RS = 51668.00
2	Making up Berms/shoulder
	Qty = 1043.35 M^2 vide T.M.B-P-29
	@ RS 56.81/M ² — RS = 58615.00
3	Repair of pot holes 75mm
	Qty = 159.399 M^3 (V.T.M.B-P-30)
	@ RS 302.66/M ³ — RS = 48243.00
4	Patch repair over Bituminous
	20mm M.S.S
	Qty = 159.72 M^2 (V.T.M.B-P-31)
	@ RS 189.26/M ² — RS = 30228.00

Continuation

C.O

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
5	Maintenance of (Drainage) (Culvert)				
	Qty = 5.08 Nos (V.T.M.B.P-31)				
	@ RS 102.25/No. —				RS = 5514.50
6	Maintenance of Road Signs.				
	Qty = 0.35 KM (V.T.M.B.P-31)				
	@ RS 1054.28/KM —				RS = 369.50
7	Maintenance of 200M x 1M Stone				
	Qty = 0.93 KM (V.T.M.B.P-31)				
	@ RS 561.09/KM —				RS = 241.50
8	Cutting of branches of tree				
	Qty = 4.00 No. (V.T.M.B.P-31)				
	@ RS 106.12/No. —				RS = 424.50
9	Trimming of grass and weeds				
	Qty = 18.00 No. (V.T.M.B.P-31)				
	@ RS 6.51/No. —				RS = 117.50
10	Trimming of grass and weeds				
	Qty = 8.98 M ² (V.T.M.B.P-32)				
	@ RS 2.17/m ² —				RS = 19.50
					RS = 195438.50
	Add GST @ 12% -				23453.00
	Add L.Cess @ 1% -				1954.00
					RS 220545.50
	Less Deduct 0.13% -				RS - 287.50
					RS 220558.00
					