

3rd year maintenance

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
N/W:- Nagra mukhya path					
Madhapur Prathmik Vidyalay					
Ue Pat to Bankaria					
Bellanda taluk via Mahanpura					
Agency:- Kapilashwar Singh					
Agreement no:- 20520/20-21					
D.O.C (actual):- 15.10.2022					

① Restoration of raincuts

12 x 2.00m x 0.70m x 0.30m = 0.42m ³					
15 x 2.50m x 0.70m x 0.30m = 7.88m ³					
9 x 2.75m x 0.70m x 0.30m = 5.20m ³					
12 x 3.00m x 0.70m x 0.30m = 8.19m ³					
21 x 3.25m x 0.70m x 0.30m = 14.33m ³					
17 x 3.50m x 0.70m x 0.30m = 12.50m ³					
19 x 3.75m x 0.70m x 0.30m = 14.96m ³					
24 x 4.00m x 0.70m x 0.30m = 20.16m ³					
16 x 4.50m x 0.70m x 0.30m = 15.12m ³					
18 x 5.00m x 0.70m x 0.30m = 18.90m ³					
21 x 6.00m x 0.70m x 0.30m = 26.46m ³					
3 x 15.00m x 0.70m x 0.30m = 9.45m ³					
2 x 10.00m x 0.70m x 0.30m = 4.20m ³					
2 x 7.00m x 0.70m x 0.30m = 2.94m ³					
					165.33m ³

② making up of berms/

Shoulder, stripping

Continuation

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
$17 \times 2.00 \text{ m} \times 0.80 \text{ m} = 27.20 \text{ m}^2$					
$4 \times 30.0 \text{ m} \times (0.80 + 0.90) \text{ m} = 102.00 \text{ m}^2$					
$8 \times 25.00 \text{ m} \times (0.80 + 0.90) \text{ m} = 170.00 \text{ m}^2$					
$10 \times 20.00 \text{ m} \times (0.80 + 0.90) \text{ m} = 170.00 \text{ m}^2$					
$14 \times 15.00 \text{ m} \times (0.80 + 0.90) \text{ m} = 178.50 \text{ m}^2$					
$14 \times 10.0 \text{ m} \times (0.80 + 0.90) \text{ m} = 129.00 \text{ m}^2$					
$9 \times 8.00 \text{ m} \times 2.70 \text{ m} = 210.60 \text{ m}^2$					
Limit Qty. = 764.44 m²					
(3) Repair of pot holes					
filled with 75 mm Bm					
$6 \times 1.60 \text{ m} \times 0.60 \text{ m} \times 0.075 \text{ m} = 0.43 \text{ m}^3$					
$8 \times 1.70 \text{ m} \times 0.80 \text{ m} \times 0.075 \text{ m} = 0.82 \text{ m}^3$					
$5 \times 1.40 \text{ m} \times 0.50 \text{ m} \times 0.075 \text{ m} = 0.26 \text{ m}^3$					
$9 \times 2.00 \text{ m} \times 1.30 \text{ m} \times 0.075 \text{ m} = 1.76 \text{ m}^3$					
$5 \times 2.00 \text{ m} \times 1.50 \text{ m} \times 0.075 \text{ m} = 1.13 \text{ m}^3$					
$2 \times 2.25 \text{ m} \times 1.40 \text{ m} \times 0.075 \text{ m} = 0.71 \text{ m}^3$					
$5 \times 2.40 \text{ m} \times 1.20 \text{ m} \times 0.075 \text{ m} = 1.08 \text{ m}^3$					
$1 \times 1.50 \text{ m} \times 1.75 \text{ m} \times 0.075 \text{ m} = 0.20 \text{ m}^3$					
Limit 6.37 m³					
(A) Patch repair over					
pot holes with 20mm					
premium Carpet					
Area of Bm = 6.29 m ²					
0.075 m					
= 85.20 m²					
$2 \times 3.00 \text{ m} \times 1.40 \text{ m} = 8.40 \text{ m}^2$					
$4 \times 3.50 \text{ m} \times 1.50 \text{ m} = 21.00 \text{ m}^2$					

C/o 114.60 m²

Continuation

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
				B/P	114.60 m ²
3 x 5.00 m x 1.50 m					19.50 m ²
2 x 5.50 m x 1.10 m					7.26 m ²
					141.36 m ²
⑤ Patch repair over bituminous surface					
Qty. Same as in no. ④					
					= 141.36 m ²
⑥ maintenance of slab					
Cikhet = 1 no.					
⑦ maintenance of road					
Sign					
					= 0.45 Km
⑧ maintenance of					
200m and Km Stones					
					= 0.54 Km
⑨ Cutting of branches of trees and Shrubs					
					= 7 nos.
⑩ Cutting of shrubs from roadway					
					= 3 nos.
Baqub					
					7.10.25
					J.E.
					07/10/25
					A.E.

ABSTRACT OF COST

60

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
① Restoration of raincuts					
Qty. vide TMBP (57)					
1. no. 1 - ① = 165.33 m ²					
@ Rs 386 = 14/m ²					
					Rs 62841 = 00
② making up of berm					
Shoulder, stripping					
Qty. vide TMBP (58)					
1. no. 1 - ② = 764.44 m ²					
@ Rs 57 = 36/m ²					
					Rs 43848 = 00
③ Repair of pot holes					
filled with form Bm					
Qty. vide TMBP (58)					
1. no. 1 - ③ = 6.37 m ²					
@ Rs 121/48 = 27/m ²					
					Rs 77384 = 00
④ Patch repair over					
pot holes with 20mm					
Qty. vide TMBP (59)					
1. no. 1 - ④ = 141.36 m ²					
@ Rs 326 = 18/m ²					
					Rs 47522 = 00
⑤ Patch repair over					
bituminous surface					
Qty. vide TMBP (59)					
1. no. 1 - ⑤ = 141.36 m ²					
@ Rs 348 = 92/m ²					
					Rs 49323 = 00
⑥ maintenance of slab					
Culvert					
Qty. vide TMBP (59)					

C/O

Continuation

Rs 216682 = 00

Rs 281918 = 00

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
1. no. :- (6) = 1 no.					
2. M 2029 = 20/no.					M 2329 = 00
⑦ maintenance of road					
sign					
Qty. wide TMBP (59)					
1. no. :- (7) = 0.45 km					
2. M 1077 = 82/km					M 485 = 00
⑧ maintenance of 200m					
Qty. wide TMBP (59)					
1. no. :- (8) = 0.54 km					
2. M 628 = 24/km					M 339 = 00
⑨ cutting of branches					
of trees and shrubs					
Qty. wide TMBP (59)					
1. no. :- (9) = 7 nos					
2. M 109 = 74/no.					M 768 = 00
⑩ cutting of shrubs					
from roadway					
Qty. wide TMBP (59)					
1. no. :- (10) = 31 nos					
2. M 6 = 73/no.					M 208 = 00
					M 286047 = 00
Less 0.08% below					M 229 = 00
					M 285818 = 00
Sequb					
7-10-25					

J.E

A.E.

Continuation