

4th & final day

33

Sch. XLV-Form No. 134

[illegible]

①	ply and applying	
	Prime coat (SS-1)	
	do. -- do as per spec	
	$10 \times 30 \times 3.75$	$= 1125 m^2$
	$10 \times 30 \times 3.75$	$= 1125 m^2$
	$10 \times 30 \times 3.75$	$= 1125 m^2$
	$10 \times 30 \times 3.75$	$= 1125 m^2$
	$1 \times 30 \times 3.75$	$= 112.5 m^2$
	$1 \times 20 \times 3.75$	$= 75 m^2$
Cume	$1 \times 8.0 \times 5.0$	$= 40 m^2$
	$1 \times 8.0 \times 5.8$	$= 46.4 m^2$
	$1 \times 10.0 \times 5.1$	$= 51 m^2$
	$1 \times 10.0 \times 4.9$	$= 49 m^2$
		$= 4843.9 m^2$
	36×3.75	$= 135 m^2$
Less		$= 4738.9 m^2$

Continuation

Continuation

[illegible]

Abstract of cost

37

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
(1/1) const ⁿ of masonry bench mark pillar vide P ⁿ (27)					
2 Nos @ 1541.75 RS.					9083=
(2/2) const ⁿ of refu pillar do - do vide P ⁿ (27)					
6 Nos @ 2098.76 RS.					12590=
(3/3) clearing and grubbing road land do - do vide P ⁿ (27)					
0.56 H ⁿ @ 76926.08					RS. 43079=
(4/4) const ⁿ of E/W up to 1000m level do - do as per vide P ⁿ (27)					
780.0m ² @ 257.77 RS.					201217=
(5/5) const ⁿ of E/W up to 100m level do - do as per vide P ⁿ (27)					
1820.1m ² @ 182.75/m ²					RS. 332805=
Continuation					RS. 598574=

Continuation