

N/W:- P.M.B.S.Y Road one Krishnas Peruviti to
Bath Wala House Tak (S.C.)
Schedule XLV-Form No. 134

31/12/19

MZ 284019

DIVISION

(220)

Agency: Aray Choudhary. SUB-DIVISION

M.B.No- 883

212311c

MEASUREMENT BOOK

31/12/19

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
ABSTRACT					
1. Restoration of RainCut with Soil vide TMB page- 38 Qty 30.28m ³ @ ₹ 365.40/m ³ = ₹ 11064.00					
2. Maintenance of Earthwork Shoulder vide TMB pg- 38 Qty 162.5m ² @ ₹ 54.39/m ² = ₹ 8838.00					
3. Maint. of bitumen mix Seal Surface vide TMB Pg No- 39 Qty. 23.44m ² @ ₹ 11.15/m ² = ₹ 4956.00					
4. Maint of Road sign vide TMB Pg. No- 39 Qty. 0.900km @ ₹ 1.088.17 = ₹ 979.00					
5. Maint. of 200 meter and km stone vide TMB Pg. No- 39 Qty - 0.900km @ ₹ 728.76/km = ₹ 656.00					
Total					₹ 26493.00
19/10/25 A.F. Continuation					

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
ABSTRACT					
1. Restoration of rain cut					
with soil vide TMB pg.					
No-42 BH 35.23 m ³					
@ ₹ 365.40/m ³ = ₹ 12873.00					
2. Maint of Gutter shoulder					
vide TMB Pg. No-43 BH					
192.5 m ² @ ₹ 54.39 = ₹ 10470.00					
3. Maint of bitumen Mix					
Seal surface vide TMB					
Pg. No-43 BH 35.16 m ²					
@ ₹ 211.45/m ² = ₹ 7435.00					
4. Patch repair on already					
field pot holes vide TMB					
Pg. No-43 BH 62.79 m ²					
@ 267.91 /m ² = ₹ 16822.00					
5. Providing and laying of hot applied					
Thumplosic. vide TMB Pg.					
No-44 BH 180 m ² @					
₹ 770.48 /m ² = ₹ 138686.00					
6. Maint of 100 m. and km share					
vide TMB Pg. No-44					

Continuation

<u>Material statement</u>		
Soil	-	35.23
Stone chips	-	2.64 m ³
Bitumen	-	186.105 kg
-		
<u>Sumit Kumar</u>	<u>Self</u>	
<u>29/10/23</u>	<u>8/10/28</u>	
<u>Tr</u>	<u>AE</u>	

