

MTAGSY 3101511 Const. of Road from -

PWD Sadak. to Musharz Tola. IT

^{Gen} Agreement No - 69/SBD/MTAGSY - 2019-20

Name of Contractor:- J.K. Satya Sai Ram

Const. Cost - 6202627.00 (INR)

Maint. Cost - 925282.00

Total - 7127909.00

Date of Commence:- 21/01/2020 MSK:

Date of Completion:- 20/01/2021

DIVISION. ARARA, Sub. Div. ARARA

M.B.No. 2029

4th Year Maintenance Bill

55

Sch. XLV-Form No. 134

[illegible]

Continuation

ABSTRACT OF COST.

59

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
1. Restoration of rain cuts					
- - - E/A					
81.00 m ²			P-58		
@ 382.29/m ²				Rs. 31055/-	
2. Maintenance of Burms					
/ Shoulder - - - E/A					
449.98 m ²			P-56		
@ 57.29/m ²				Rs. 25779/-	
3. Repair to pot holes					
with B.M. - - - E/A					
5.38 m ²			P-57		
@ 10551.28/m ²				Rs. 56555/-	
4. Patch repair on already filled pots - - - E/A					
71.52 m ²			P-57		
@ 203.64/m ²				Rs. 14566/-	
5. Repair to pot holes with M.S. - - - E/A					
71.53 m ²			P-57		
@ 203.64/m ²				Rs. 14566/-	
6. Maintenance of slab					
curb - - - E/A					

Continuation

61
Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
			17		149288 =
Add GST @ 12%					17915 =
Add L-Less @ 1%					1493 =
					168636 =
Less below @ 0.21%					(-) 354 =
					168342 =

3/9/15
J.E

Material Statement

Coarse Sand -	0.86 m ³
Stone Chips -	4.29 m ³
Bitumen -	0.626 MT
Sand -	113.25 m ³

3/9/15
J.E

Continuation