

Jitvax to Khanani

Schedule XLV Form No. 134.

1013.110-791

PPSMP

PIRO

DIVISION

PIRO

SUB-DIVISION

Conteiam - (Holligrock Instansatayctye Pnt. Ltd)

Madehngg kr (Jiv)

Measurement Book

①	Construction of unsie-
	inforced, dowel jointed
	PCC pavement
for profile correction	$7 \times 5.10 \times 1.85 \times 0.075 = 4.953$ m ³ $9 \times 4.50 \times 2.05 \times 0.100 = 8.303$ m ³ $9 \times 3.70 \times 1.35 \times 0.085 = 3.831$ m ³ $8 \times 5.90 \times 2.15 \times 0.100 = 10.148$ m ³ $1 \times 7.20 \times 2.15 \times 0.110 = 1.703$ m ³ $1 \times 8.10 \times 2.35 \times 0.105 = 1.999$ m ³
for Existing PCC	$1 \times 30.00 \times 3.75 \times 0.125 = 14.063$ m ³ $3 \times 30.00 \times 3.75 \times 0.125 = 42.188$ m ³ $2 \times 30.00 \times 3.75 \times 0.125 = 28.125$ m ³ $1 \times 30.00 \times 3.75 \times 0.125 = 14.063$ m ³ $2 \times 30.00 \times 3.75 \times 0.125 = 28.125$ m ³

Continuation

Continuation