

Name of work

Habitation to Habitation

Schedule XLV Form No. 134.

Agency — Sanjay Kumar
Baroli Executive Engineer
R.W.D. Works Division
Raipur

DIVISION

A.E. Narhat

SUB-DIVISION

M.B. No. 1064

Measurement Book

3rd Year Maint.
43

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Name of Road - Construction of					
Road from Habitation to					
Habitation					
Agency -					
Agreement No -					
Actual Date of Completion -					

① Restoration of Rain cut.

with soil.

— do — do —

4x 3.10m x 1.35m x 0.30m = 5.02m³

6x 5.10m x 1.20m x 0.30m = 11.02m³

5x 9.30m x 1.50m x 0.30m = 20.93m³

3x 6.25m x 1.30m x 0.30m = 7.31m³

4x 4.50m x 1.50m x 0.30m = 8.10m³

5x 5.20m x 1.30m x 0.30m = 10.14m³

3x 2.10m x 1.30m x 0.30m = 2.46m³

Total 64.97m³

② Maintenance of Ditch

Shoulder

— do — do —

Continuation

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
2x 5x 30.00m x 0.95m					285.00m ²
2x 2x 27.70m x 0.70m					77.00m ²
					Total: 362.00m ²
(3) Repair to port holes by					
removing old failed material.					
do do do					
4x 2.10m x 1.90m					15.96m ²
2x 4.30m x 1.30m					11.18m ²
1x 1.20m x 1.20m					1.44m ²
1x 2.40m x 0.90m					2.16m ²
2x 0.90m x 1.20m					2.16m ²
					Total: 32.90m ²

(4) maintenance at WBM					
Road including filling.					
do do do					
4x 2.10m x 1.90m					15.96m ²
2x 4.30m x 1.30m					11.18m ²
1x 1.20m x 1.20m					1.44m ²
1x 2.40m x 0.90m					2.16m ²
2x 0.90m x 1.20m					2.16m ²
					Total: 32.90m ²

(5) Port Repair on already					
filled port holes					
do do do					
4x 2.10m x 1.90m					15.96m ²

Continuation

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
2x4.30mX 1.30m 2					11.18m ²
1x1.20mX 1.20m 2					1.44m ²
1x2.40mX 0.90m 2					2.16m ²
2x 0.90mX 1.20m 2					2.16m ²
				Total:	32.90m ²
(6) maintenance of Road					
marking with Hot Applied					
on Bituminous surface					
2x 15x 30.00mX 0.10m 1					90.00m ²
2x 1x 20.00mX 0.10m 1					4.00m ²
					94.00m ²
(7) maintenance of Road					
on concrete surface					
2x 15x 30.00mX 0.10m 1					90.00m ²
(8) maintenance of Road					
Signs					
				0.920km	
(9) maintenance of Road					
km stone					
				0.166 km	

Continuation

Continuation

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Abstract at cost					
(1) Restore ab. Rainscut					
with soil.					
64.97 m ² vide T.m.B P-43.					
64.97 m ² @ 773.94/m ²					
					= M 50283.00
(2) maintenance ab. Road					
shoulder					
362.00 m ² vide T.m.B P-44					
362.00 m ² @ 57.92/m ²					
					= M 20,967.00
(3) Repair to Pot hole by					
removing ab.					
32.90 m ² vide T.m.B P-44					
32.90 m ² @ 255.37/m ²					
					= M 8402.00
(4) maintenance ab. W.B.M					
Road widening.					
32.90 m ² vide T.m.B P-44					
32.90 m ² @ 190.24/m ²					
					= M 6258.00
(5) Patch Repair on already					
filled pot hole.					
32.90 m ² vide T.m.B P-45					
32.90 m ² @ 238.46/m ²					
					= M 7845.00

Continuation

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
(6) maintenance ab Road					
marking with Hot					
on B.I. portions -					
94.00m ² wide T.m.B				P-45	
94.00m ² @ 1444.200/m ²					
					= Rs 1,35,736.00
on concrete surface -					
90.00m ² wide T.m.B				P-45	
90.00m ² @ 1620.200/m ²					
					= Rs 1,45,800.00
(7) maintenance ab Hume pipe					
Culvert					
01 Nos. wide T.m.B				P-45	
01 Nos. @ 1130.62/m ²					
					= Rs 1,131.00
(8) maintenance ab Road					
Sign					
0.920 km wide T.m.B				P-45	
0.920 km @ 1077.81/km					
					= Rs 992.00
(9) maintenance ab Zoom Stone					
0.166 km wide T.m.B				P-45	
0.166 km @ 2072.02/km					
					= Rs 117.00
(10) Trimming ab Grass area					
Woods					
776.25m ² wide T.m.B				P-46	
776.25m ² @ 2524/m ²					
					= Rs 17,391.00

Continuation

